



Your Ref: 0358460838SG003

Date: 23rd Nov 2022

Our Ref: CS1/AIG22010981/Eqy3e2

M/s AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #09-16

Aig Building

Singapore 079120

(The Motor Claims Department)

Attn: Angie Gan

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLU 5507U

INSURED VEHICLE: GZ 57S

ACCIDENT DATE: 14/10/2019

We thank you for your instruction on 02/11/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLU 5507U from M/s Automax Survey.
- b) Singapore Accident Statement of Vehicles SLU 5507U and GZ 57S.
- c) Colour damaged vehicle photographs of SLU 5507U.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLU 5507U
Make & Model	: Toyota Vios E Auto
Year of Registration	: 2009
Chassis Number	: MR053HY9305100794
Engine Capacity	: 1497 cc

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.