

Server:

Special Instruction:

LS : \$10000 / 10 DAYS

Third Parties:

Claimant:

OD/TP Re-inspection / Evaluation

Workshop: HUP LEY HUAT MOTOR
SPRAY PAINTING SVS

at Workshop m/s HUP LEY HUAT MOTOR SPRAY PAINTING SVS

of ~~BLK 1 KAKI BUKIT AVE 6, #01-35 AUTOBAY SINGAPORE 417883~~

Policy No: _____ Claim No: 0358460838SG003

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 14/10/2019
(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 23/11/22 Confirmed with _____ Final Fig _____, ____ days (Red \$ ____/____%; Original! ____ days)

Date/Time: 23/11/22 Submit ~~Final Fig~~ LS \$4100, 7 days (Red \$ 5900 / 59%; Original 10 days)

Para(1) : Parts found not replaced	(To highlight <i>R or UB, LR, Etc</i>)
------------------------------------	---

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Date:

Basic & Add

Transport

Photos

Others

Total

1) Date/Time 23/11/22 File Pass to Typist

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____