



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWERSINGAPORE 048623

Ref: CS/SMO22010991/Avy3e2

Date: 23/03/2023

Code: SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GZ 4517E	Veh. Inspected	SJP 7390A
Policy No.	D22MTPCVE000990	Coverage (\$)	0.00
Claim No.	CMTD2203970/RUC	Excess (\$)	0.00
Assign From	IRENE HENRY	Assign Date	03/11/2022

2. Vehicle Particulars & Condition

Make & Model	HONDA FIT	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	GE61158296	Colour	RED
Odometer	238643 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R14	YOKOHAMA	6 mm
L/H Front Tyre	175/70 R14	YOKOHAMA	6 mm
R/H Rear Tyre	175/70 R14	YOKOHAMA	6 mm
L/H Rear Tyre	175/70 R14	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/11/2022	Inspection Date	03/11/2022
Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **12 Working Days**