AS RECOBY: STEVE TO SCTIPP	01/007/Egp3
ASSIGNMENT	
From: Date:	Veh No: 3NF 782/M/ Yr Regn: 07/6/72
Estimated Cost:	Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover
OD TEL WELTE REST OD REST EVA LINVINV	Truck / Traller or
To Inspect Vehicle No:	Make: BMW 2181 c.c 1099
et Workshop m/s	Colour 3/9(A/C: Insured / Std / NI / NA
vi .	Sp.Reading 3576 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CNO: WISA 6 V 1/10/00 50 68411
Claims No.	Gen. Cond: Good Fair / Poor / Burnt Steering: Inorger / Jammed / Leaked / Burnt or
Sum Insured: Excess:	Brake: Inorder/Jammed/Leaked/Burnt or
(Client's Record)	Modi: Nil / S/R/m / STD A/Rim or
Make of Veh;	116/1/0016
	Tyre Size: F:
(Policy Condition) Person The year had commenced its	BS I DUN I EXNOVA I CY I FS I LIZA I MIC I OHTSU I PIR I SUMII
Remark: The veh had commenced its repair at the time of inspection.	TOYO/YOKO or .
	Front Rear 1()
Bal. or Market Value: IDAC Accident Rport: Consistent? : Yes or No	R/Bal. R/Bal. Wmm R/Bal.
GIA / PR Seen: Consistent? : Yes or No	UBal. UBal. UBal.
2 Page Voc of No	D.O.A. 7/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1
Est Repairs: 3 days Res.: Yes or No	Survey held at Performance
	Des. of Damages: Frt Rear Ols (N/3 U/C Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OU	The U/C / Chassis frame / Body Structure affected due to collision.
Date: Person Contacted:	The U/C / Chassis frame / Body Stitutions allocated
Date / Time Action / Instruction ,	
——————————————————————————————————————	or the costs of repairs in \$5183.70 and 3 days.
(red, \$2208,	30%)
The state of the s	
Oste/Time, File Pass to? : Prell. Report	Days Of Repair: 3
OAIOAIOO Final Papart	Resurvey No. of Trip: 1 Survey Fee:
Date/Time, File Return to?	Transportation:
Add	
	: Interview (\$) Photos
Repart Formet:tp	:Tech, Invs (\$) Others
Lump 3mm/1.8.1: (# 5183.70 .)	: Weelland (%)
· · · · · · · · · · · · · · · · · · ·	
the second of th	