

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC3832K
MAKE HYUNDAI
MODEL IONIQ

DATE: 29.07.22
MVA JUMANI
DOA: 28.05.22

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			\$459.40
1	REAR BUMPER CENTRE MOULDING			\$451.25
1	REAR BUMPER BEAM			\$394.80
10	REAR BUMPER CLIPS			\$22.00
1	ANTENNA SMARTKEY			\$40.50
1	FOG LAMP			\$201.50
1	NUMBER PLATE LAMP (LH/RH)		\$85.30	\$170.60
1	REAR UNDER LOWER COVER			\$155.00
1	REAR UNDER CENTRE UNDER COVER			\$225.00
1	TOW COVER			\$98.80
1	BOOT LAMP ASSY RH			\$822.00
	SUB TOTAL			\$3,040.85
	LESS 20%			\$608.17
	DISCOUNTED TOTAL			\$2,435.68
	REAR NUMBER PLATE			\$50.00
	REVERSE SENSOR			\$180.00
	ADVERTISEMENT LOGO- FENDER			\$200.00
				\$430.00
	Labour Charge			
	PANEL BEATING			\$1,200.00
	SPRAY PAINT			\$600.00
	REMOVE / REFIX REVERSE SENSOR			\$50.00
	CHECK WIRING			\$50.00
	TOTAL LABOUR			\$1,900.00
	ESTIMATE TOTAL			\$4,762.68
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

CPLP)

nn

nec

nn

nn

nn

nn

NET

NET

NET nn

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

58 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

48 Pandan Road Singapore 609286

320 Ubi Road Singapore 708649

24 Serangoon Loop Singapore 758156

7 Sungei Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 768732

Date/Time: 28.10.2022 08:43

Page : 1

Job: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5131786

JC NO: 305534760

OWNER COMFORT TRANSPORTATION PTE LTD IS 7010045 OWNER NO. 383 SIN MING DRIVE ADDRESS Singapore SINGAPORE 575717 (R) 65508755 (O) (P)	REGN NO. SHC3832K	MILEAGE
	MAKE HYUNDAI	FUEL E.....1/2.....F
	MODEL IONIQ(G3)	DATE/TIME IN 28.10.2022 16:00
	YR OF MANU. 07.11.2019	TARGET DATE
	CHASSIS CODE RMHC851CVLU188165	COMPLETION DATE/TIME:

QUANTITY CARD NO.

JOB DESCRIPTION


Accident Date: 28.10.2022

ATURE: 3P.28.10.22

NO

LABOR CODE

DESCRIPTION



BOOKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Redemption Slip

Exit Pass

No.: SHC3832K

JU CHINA

Vehicle No.:

SHC3832K

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard