

08/11/13, wef

REF:

CS/LIP 22011031/Uny3

ASS REC. BY: Marcus

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No. AVS22/3047

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal.

D.O.I.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2) 9/12/22-typist

Report Format: TP

Lump Sum / +B. (\$ 2900)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

Survey Fee:


Transportation:

) S + RS, SI

) Photos

) Others

TOTAL



\$17k.

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

3446

Vehicle: IN / OUT

LTA \$ 3172

9/12/22 1/5 \$ 2900 : indom nll Kien (red 8251, 73%)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	344G
Vehicle Details	
Vehicle No.:	EDR1938U
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Nov 2022
Vehicle Make:	YAMAHA
Vehicle Model:	CZD300A / XMAX300
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	H336E0069881
Chassis No.:	MH3SH0847LK009586
Maximum Power Output:	-
Open Market Value:	\$4,463.00
Original Registration Date:	16 Mar 2020
First Registration Date:	16 Mar 2020
Transfer Count:	3
Actual ARF Paid:	\$670.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Mar 2030
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$4,310.00
COE Rebate Amount:	\$3,172.00
Total Rebate Amount:	\$3,172.00

The information contained herein is correct as at 05 Nov 2022

OK

Vehicle Type : Scooters

Mileage : 34300km


SGD \$20600

Posted on : 27/10/2022

★ Paid Ad

★ Dealer Ad

Details >



Yamaha Xmax 300

Reg Date : 19/03/2019

Capacity : 292cc

Vehicle Type : Scooters

Mileage : -


SGD \$17500

Posted on : 27/10/2022

★ Paid Ad

★ Dealer Ad

Details >



Yamaha Xmax 300

Reg Date : 10/02/2018

Capacity : 292cc

Vehicle Type : Scooters

Mileage : 69151km

SGD \$15800

Posted on : 12/10/2022

★ Paid Ad

★ Dealer Ad

Details >



Yamaha Xmax 300

Reg Date : 21/07/2021

Capacity : 292cc

Vehicle Type : Scooters

Mileage : -

SGD \$20500

Posted on : 12/10/2022

★ Paid Ad

★ Dealer Ad

Details >



Yamaha Xmax

Reg Date

Vehicle Type

Posted on : 21/10/2022

★ Direct Seller

Details >



Bike model

Yamaha Xmax 300

Search

Type Of Vehicle

Any

Price From

Any

Price To

Any


Class

Any

More Search Options ▾

Sort By

Recommended



Yamaha Xmax 300

Reg Date : 02/07/2019

Capacity : 292cc

Vehicle Type : Scooters

Mileage : -


SGD \$17200

Posted on : 31/10/2022

★ Paid Ad

★ Dealer Ad

Details >



Yamaha Xmax

Reg Date : 03/01/2020

Capacity : 292cc

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

4/5 \$2900

ESTIMATE COST OF REPAIR

Date: 2-Nov-22

Estimate no.

1178

Plate No. FBR1938U

Model. XMAX 300

not authorized
HKK
Tel: 62563561
L/S \$ 2900
48 days

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	EXHAUST PIPE	11 \$ 950.00	X	
2	EXHAUST COVER 1	50 \$ 180.00	X	
3	EXHAUST COVER 2	50 \$ 150.00	X	
4	REAR SPORT RIM	negot \$ 550.00	2	
5	REAR TYRES	11 \$ 220.00	X	
6	RAER DISC BRAKE	11 \$ 280.00	X	
7	REAR SWING ARM	11 \$ 350.00	X	
8	REAR SUSPENSION	11 \$ 480.00	X	
9	RAER FAIRING COVER RIGHT	2 \$ 300.00	X	
10	REAR BILLION BAR RIGHT	2 \$ 180.00	X	
11	FRONT FORK SET	11 \$ 800.00	X	
12	FRONT FENDER SIDE COVER	cur \$ 120 200.00	✓	
13	FRONT TYRES SHAFT	11 \$ 180.00	X	
14	HEAD LIGHT	cur \$ 600 850.00	✓	
15	FRONT FAIRING COVER LEFT	cur \$ 300.00	✓	
16	PANEL COVER	2 \$ 250.00	X	
17	FRONT FAIRING PANEL COVER LEFT	cur \$ 220.00	✓	
18	FRONT FOOTREST BOARD COVER LEFT	cur \$ 100 250.00	✓	
19	FRONT FOOTREST UNDER COVER LEFT	cur \$ 180.00	✓	
20	BODY UNDER COVER	cur \$ 162 300.00	✓	
21	HANDLE BAR	2nd \$ 185 280.00	✓	
22	BRAKE LEVEL	cur \$ 100.00	✓	
23	HANDLE BAR END	cur \$ 30 120.00	✓	
24	MAINSTAND	cur \$ 180 350.00	✓	
25	AIR BOX COVER X2	cur \$ 180.00	✓	
26	CVT HOUSING COVER	cur \$ 150.00	✓	
27	REAR FAIRING COVER LEFT	cur \$ 220 300.00	✓	
28	REAR BILLION BAR LEFT	2 \$ 180.00	X	
29	REAR MADGUARD	2 \$ 140 150.00	✓	
30	REAR NUMBER PLATE	cur \$ 30.00	20 3/N	

102

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*

This is computer generated no signature is required.

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 2-Nov-22

Estimate no. 1178

Plate No. FBR1938U

Model. XMAX 300

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
31	SPRAY COVERSET	\$ 600.00	200	
32	STEERING CONE	17 \$ 320.00	X	
33	MASTER PUMP LEFT	R \$ 280.00	X	
34	HEAD LAMP STAY	17 \$ 300.00	X	
35	FORL T-UNDER BRACKET	17 \$ 400.00	X	
36	FRONT SPORT RIM	17 \$ 500.00	X	
37	HANDLE BRACKET	17 \$ 280.00	X	
38	LABOUR	\$ 700.00	300	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Less 10% \$ 1,239.00

Sub Total : \$ 11,151.00

GST 7% \$ 780.57

Total: \$ 11,931.57

P-3477
102
3129.30
20
1200
3649.3
22
2919.

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*

This is computer generated no signature is required.