

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 Code: CTI 1. Policy Particulars: - THIRD PARTY CLAIM Insured Veh. SKB 9467L Veh. Inspected SGK 6278K Policy No. DMPCSNW00154552100 Coverage (\$) 0.00 Claim No. SNM22D200951/C02/CHNGPW Excess (\$) 0.00 Assign From ADELINE CHNG Assign Date 03/11/2022 2. Vehicle Particulars & Condition Make & Model NISSAN X-TRAIL 2.0 CVT c.c 1997 Engine No. HIDDEN Year of Reg. 2016 Chassis No. JN1JANT32Z0002260 Colour WHITE	Rvp3e2-1
Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM Insured Veh. SKB 9467L Veh. Inspected SGK 6278K Policy No. DMPCSNW00154552100 Coverage (\$) 0.00 Claim No. SNM22D200951/C02/CHNGPW Excess (\$) 0.00 Assign From ADELINE CHNG Assign Date 03/11/2022 2. Vehicle Particulars & Condition Make & Model NISSAN X-TRAIL 2.0 CVT c.c 1997 Engine No. HIDDEN Year of Reg. 2016	
Insured Veh. SKB 9467L Veh. Inspected SGK 6278K	
Policy No. DMPCSNW00154552100 Coverage (\$) 0.00 Claim No. SNM22D200951/C02/CHNGPW Excess (\$) 0.00 Assign From ADELINE CHNG Assign Date 03/11/2022 Vehicle Particulars & Condition Make & Model NISSAN X-TRAIL 2.0 CVT c.c 1997 Engine No. HIDDEN Year of Reg. 2016	
Claim No. SNM22D200951/C02/CHNGPW Excess (\$) 0.00 Assign From ADELINE CHNG Assign Date 03/11/2022 Vehicle Particulars & Condition Make & Model NISSAN X-TRAIL 2.0 CVT c.c 1997 Engine No. HIDDEN Year of Reg. 2016	
Assign From ADELINE CHNG Assign Date 03/11/2022 Vehicle Particulars & Condition Make & Model NISSAN X-TRAIL 2.0 CVT c.c 1997 Engine No. HIDDEN Year of Reg. 2016	
2. Vehicle Particulars & Condition Make & Model NISSAN X-TRAIL 2.0 CVT c.c 1997 Engine No. HIDDEN Year of Reg. 2016	
Make & ModelNISSAN X-TRAIL 2.0 CVTc.c1997Engine No.HIDDENYear of Reg.2016	
Engine No. HIDDEN Year of Reg. 2016	
Chassis No. JN1JANT32Z0002260 Colour WHITE	
Odometer 52844 KM Steering IN ORDER	
Brakes IN ORDER Modification SPORTS RIM	
General FAIR	
3. Conditions of Tyres	
Size Make Balance	
R/H Front Tyre 225/60 R18 LAUFENN 6 mm	
L/H Front Tyre 225/60 R18 LAUFENN 6 mm	
R/H Rear Tyre 225/60 R18 LAUFENN 6 mm	
L/H Rear Tyre 225/60 R18 LAUFENN 6 mm	
4. Description of Damages	
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.	
DAMAGES SEE DETAILS.	
5. General Information	
Accident Date 08/02/2022 Inspection Date 14/02/2022	
Survey held at 5 Yishun Ind Street #01-20 North Spring BizHub	
Repairer ONE ZONE AUTOMOTIVE LLP	
5a. Remarks	
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	
5b. Estimate Days of Repair	
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days	