ALS. FEG. BY: 05 MSG 22011051 DWY	
AS	SSIGNMENT
From: Date:	Veh No: 8MT 8464+ Yr Regn: July 12020
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Toyota Covollo Hybrige 1798
at Workshop m/s	Colour White A/C: Insured / Std / Ni / NA
of	Sp.Reading 39279 T/Radio: Insured / Std / NI / NA
nsured:	Eng/No: 27R2C27511
Policy No.	C/No: JTHK 93BE403003650
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 205 55 72 16
(Policy Condition)	R:
demark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO OF Dunlop
al. or Market Value: \$105,000	Front Rear
OAC Accident Rport: Consistent? : Yes or No	R/Bal. / mm R/Bal. // mm
IA / PR Seen: Consistent?: Yes or No	L/Bal. \(\sqrt{mm} \) L/Bal. \(\sqrt{y} \) mm
st. Repairs: 2 days Res.: Yes or No	D.O.A. 02 11/2022 D.O.I. 07/11/2022
um Sum: % 3 Val.: Yes or No	Survey held at CS ong AMK
A / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OU'	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
MS1G SKR 37618	
10.00	
2/23 Judgel 2/3 1,800/- with	3 day 7 4 (Red \$15,958.72/90%
MV=\$105,000 ; LTA- \$36,361 ; NV-	\$68,639
1,1,2,1,00,001,111	-
	· · · · · · · · · · · · · · · · · · ·
e/Time, File Pass to?	
01/03/2023 Fren. Report	Days Of Repair: 3
TYPIST : Final Report e/Time, File Return to?	Resurvey No. of Trip: Survey Fee:
Add Fe	Transportation:
\	3+RS_SI
	: Interview (\$) Photos