

REF: CS/CTI22011053/Rvp3

Special Instruction:

L/SUM: 11,500 / WORKING DAYS OF REPAIR: 13

ASSIGNMENT (Office)

From (Person): TAN KAH LEONG of CHINA TAIPING Date/Time: 04/11/2022

Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant:

Surveyor: AUTOMOTIVE APPRAISER

Workshop: HIAP LEK AUTOMOBILE TRADING

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: GBD 230H Insured: GBF 7430R

at Workshop m/s HIAP LEK AUTOMOBILE TRADING

of 160 SIN MING DRIVE #05-17 SIN MING AUTOCITY SINGAPORE 575722

Policy No: _____ Claim No: SNM22D204666/C02

Sum Insured: _____ Excess: _____

Make of Veh: _____
(Client's Record) _____ D.O.A. 04/07/2022

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig _____, ____ days (Red \$____/____%; Original ____ days)

Date/Time: _____ Submit Final Fig _____, ____ days (Red \$ _____/____%; Original ____ days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	
--	--

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

1) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____