

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	CHINA TAIPING IN	ISURANCE (S) PTE LTD	Ref:	CS/CTI22011053/Rvp3e2	
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909	Date	07/03/2023	
			Code	: CTI	
1.	Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	GBF 7430R	Veh. Inspected	GBD 230H	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	SNM22D204666/C02	Excess (\$)	0.00	
	Assign From	TAN KAH LEONG	Assign Date	04/11/2022	
2. Vehicle Particulars & Condition					
	Make & Model	NISSAN NV200	c.c	1461	
	Engine No.	HIDDEN	Year of Reg.	2014	
	Chassis No.	VSKYBAM20Z0077960	Colour	SILVER	
	Odometer	188889 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	175/70 R14	FALKEN	5 mm	
	L/H Front Tyre	175/70 R14	FALKEN	5 mm	
	R/H Rear Tyre	175/70 R14	FALKEN	5 mm	
	L/H Rear Tyre	175/70 R14	FALKEN	5 mm	
4.	Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
	REPAIR CONDITION SEE DETAILS.				
5.	General Information				
	Accident Date	04/07/2022	Inspection Date	14/11/2022	
	Survey held at	rvey held at HIAP LEK AUTOMOBILE TRADING			
	160 SIN MING DRIVE #05-17 SIN MING AUTOCITY SINGAPORE 575722				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days				
	•				