



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22011063/Avy3q2 Date: 13/02/2023	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLP 3285Z	Veh. Inspected	SMK 4708D	
Policy No.	P10169389R03	Coverage (\$)	0.00	
Claim No.	C10018435/JY	Excess (\$)	0.00	
Assign From	SALIZAWATI HAIZAR	Assign Date	04/11/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	KIA CERATO	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KNAF3416MK5036904	Colour	GREY	
Odometer	63128 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/65 R17	PIRELLI	6 mm	
L/H Front Tyre	225/65 R17	PIRELLI	6 mm	
R/H Rear Tyre	225/65 R17	PIRELLI	6 mm	
L/H Rear Tyre	225/65 R17	PIRELLI	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	03/11/2022	Inspection Date	07/11/2022	
Survey held at	J-MART MOTOR PTE LTD BLK 5 DEFU LANE 10 #01-578 DEFU INDUSTRIAL PARK C SINGAPORE 539186			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		