

Steve


CS/CT1 22/11/07/Exp3

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
☒ TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop n/s \_\_\_\_\_  
 of \_\_\_\_\_  
 insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: 2000  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bas. or Market Value: 120k  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 G/A / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 7 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: XE 3031E Yr Regn: 6/6/17  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Traller or  
 Make: Man TG8 c.c. 10.518  
 Colour: White A/C: Insured / Std / NI / NA  
 Sp. Reading: 48818 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WMA26S229 HM 742151  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modl: Nil / S/Rim / STD / Rim or  
 Tyre Size: F: 315/80R22.5  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /  
 TOYO / YOKO or FIRMAX  
 Front Rear  
 R/Bal. 4 mm R/Bal. 4 mm  
 L/Bal. 4 mm L/Bal. 4 mm  
 D.O.A. 31/10/22 D.O.I. 7/11/22  
 Survey held at GCH Bell  
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop of  
Front RH  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instructions

N/V- 120k

We will be advising our principal a cost of repair of \$27,822.93

before excess \$2,000.00 & GST with 7 days of repair, subject to their approval

(red, \$15991.35, 36%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Repair Format: \_\_\_\_\_

Lump Sum / L.B.B. (\$) \_\_\_\_\_

Days Of Repair: 7

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

: Site Insp (\$ \_\_\_\_\_)

☐

: Interview (\$ \_\_\_\_\_)

☐

: Tech. Insp (\$ \_\_\_\_\_)

☐

: Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\$ + P.S. \$ \_\_\_\_\_

Procs

Others

TOTAL



# GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.  
41,000 Served. And Counting.

## GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676  
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 9207 Fax: 6862 3500  
Website: [www.goldbell.com.sg](http://www.goldbell.com.sg)  
Co. Reg. No.: 199005563G

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

### PARTICULARS OF CLAIM

|                               |                                                                                                                              |                       |                   |
|-------------------------------|------------------------------------------------------------------------------------------------------------------------------|-----------------------|-------------------|
| Claim Type:                   | OD (Own Damage)                                                                                                              | Ref. No:              | XE3031E           |
| Policy No:                    | DMCVSNW00058462201                                                                                                           | Date of Loss:         | 31/10/2022        |
| Vehicle Reg. No.:             | XE3031E                                                                                                                      | Driveable?            |                   |
| Driver Age/Info:              | / MALE                                                                                                                       | Party At Fault:       | UNKNOWN           |
| TP Injury Involved?           | NO                                                                                                                           | Third Party Involved? | YES               |
| Insured/Claimant:             | HIAP SENG TRANSPORT PTE LTD                                                                                                  |                       |                   |
| Driver:                       | ZHANG QIANGXIANG                                                                                                             |                       |                   |
| Make/Model:                   | MAN TGS 26.400, 10.5 D 6X4 BBS (M)                                                                                           | Vehicle Reg. Date:    | 06/06/2017        |
| Vehicle Colour:               | White                                                                                                                        | Chassis No:           | WMA26SZZ9HM742151 |
| Engine No:                    | 50547181714720                                                                                                               |                       |                   |
| Odometer:                     | 0 KM                                                                                                                         |                       |                   |
| Paint Type:                   |                                                                                                                              |                       |                   |
| Total Loss?                   | NO                                                                                                                           |                       |                   |
| Est. Duration of Repair (day) | 15                                                                                                                           |                       |                   |
| Remarks:                      | KINDLY CONTACT OUR MOTOR CLAIMS OFFICER SI MING (9739 7127) FOR SURVEY, VEHICLE IS IN THE WORKSHOP AT 8 TUAS AVE 18 S638892. |                       |                   |
| Present Location:             | GOLDBELL ENGINEERING PTE LTD (TUAS)                                                                                          |                       |                   |

| COST OF CLAIMS            | Amount           |
|---------------------------|------------------|
| Parts                     | 26,807.44        |
| Miscellaneous Items       | 480.00           |
| Labour                    | 6,900.00         |
| Paintwork Labour          | 0.00             |
| Towing                    | 0.00             |
| <b>Gross Total (\$\$)</b> | <b>34,187.44</b> |
| <b>+ GST 7.00% (\$\$)</b> | <b>2,393.12</b>  |
| <b>Nett Amount (\$\$)</b> | <b>36,580.56</b> |

This claim is handled by: LIEW SI MING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

# REPAIR DETAILS

## Reference

Part Source: (Last Synchronised: 03 Nov 2022)  
 Parts: N/A MAN TGS 26.400 10.5 D 6X4 BBS (M) (Model not available in database)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: Goldbell Engineering Pte Ltd/XE3031E/03/11/2022 14:51  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

| No. | Qty | Part No. | Particulars                                        | %Disc | %Depr | Amount               |
|-----|-----|----------|----------------------------------------------------|-------|-------|----------------------|
| 1   | 1   |          | *FRONT SERVICE DOOR nn                             | 0.00  | 0.00  | -                    |
| 2   | 1   |          | *FRONT SERVICE DOOR ASSY / DD (FWD PM)             | 0.00  | 0.00  | *2,931.36 F ✓        |
| 3   | 2   |          | *RUBBER STOP X nn                                  | 0.00  | 0.00  | *20.70 F ✓           |
| 4   | 1   |          | *WIND DEFLECTOR RH MIS                             | 0.00  | 0.00  | *158.71 F ✓          |
| 5   | 1   |          | *WIND DEFLECTOR RH PRIMED MIS                      | 0.00  | 0.00  | *447.30 F ✓          |
| 6   | 12  |          | *GROOVED OVAL HEAD SCREW nec                       | 0.00  | 0.00  | 31.75 ✓ *31.80 F ✓   |
| 7   | 1   |          | *BRACKET MIS                                       | 0.00  | 0.00  | *27.94 F ✓           |
| 8   | 1   |          | *COVERING RH MIS                                   | 0.00  | 0.00  | *15.61 F ✓           |
| 9   | 1   |          | *BRACKET RH MIS                                    | 0.00  | 0.00  | *164.79 F ✓          |
| 10  | 1   |          | *PILLAR LINING OUTER nn                            | 0.00  | 0.00  | -                    |
| 11  | 1   |          | *PILLAR LINING RH PRIMED OR                        | 0.00  | 0.00  | *515.76 F ✓          |
| 12  | 1   |          | *WATER DEFLECTOR RH X nn                           | 0.00  | 0.00  | *14.28 F ✓           |
| 13  | 1   |          | *MIRROR TRIM RH DOOR HINGE MIS                     | 0.00  | 0.00  | *47.79 F ✓           |
| 14  | 1   |          | *COVERING MIS                                      | 0.00  | 0.00  | *8.34 F ✓            |
| 15  | 1   |          | *MOULDED FOAM RH, UPPER X nn                       | 0.00  | 0.00  | *33.72 F ✓           |
| 16  | 2   |          | *GROOVED OVAL HEAD SCREW nec                       | 0.00  | 0.00  | 5.29 ✓ *5.30 F ✓     |
| 17  | 4   |          | *SNAP NUT nec                                      | 0.00  | 0.00  | *15.84 F ✓           |
| 18  | 1   |          | *STEEL BUMPER CENTRE PART nn                       | 0.00  | 0.00  | -                    |
| 19  | 1   |          | *STEEL BUMPER MIDDLE SECTION POWDER-COATED X DD nn | 0.00  | 0.00  | *2,493.18 F ✓        |
| 20  | 10  |          | *WASHER X nn                                       | 0.00  | 0.00  | *207.90 F ✓          |
| 21  | 10  |          | *12 POINT SOCKET X nn                              | 0.00  | 0.00  | *263.40 F ✓          |
| 22  | 1   |          | *STEEL BUMPER CORNERS nn                           | 0.00  | 0.00  | -                    |
| 23  | 1   |          | *STEEL BUMPER POWDER-COATED RH DD                  | 0.00  | 0.00  | *1,913.67 F ✓        |
| 24  | 1   |          | *CARRIER HEADLAMP RH MIS                           | 0.00  | 0.00  | *289.68 F ✓          |
| 25  | 1   |          | *PIN MIS                                           | 0.00  | 0.00  | *97.74 F ✓           |
| 26  | 1   |          | *SUPPORT MIS                                       | 0.00  | 0.00  | *78.12 F ✓           |
| 27  | 1   |          | *BRACKET HEADLAMP RH MIS                           | 0.00  | 0.00  | *40.95 F ✓           |
| 28  | 1   |          | *BRACKET FLASHER RH MIS                            | 0.00  | 0.00  | *14.53 F ✓           |
| 29  | 1   |          | *STEEL BUMPER TRIM nn                              | 0.00  | 0.00  | -                    |
| 30  | 1   |          | *BUMPER END PANEL RH MIS                           | 0.00  | 0.00  | *62.95 F ✓           |
| 31  | 2   |          | *LINE CLIP nec                                     | 0.00  | 0.00  | 5.11 ✓ *5.12 F ✓     |
| 32  | 1   |          | *STEPWELL LOWER nn                                 | 0.00  | 0.00  | -                    |
| 33  | 1   |          | *STEPWELL RH OR DT                                 | 0.00  | 0.00  | *1,420.38 F ✓        |
| 34  | 1   |          | *STEP SILVER-METALLIC DT                           | 0.00  | 0.00  | 272.82 ✓ *272.83 F ✓ |
| 35  | 1   |          | *HEADLAMPS nn                                      | 0.00  | 0.00  | -                    |
| 36  | 1   |          | *HEADLAMP RH MIS                                   | 0.00  | 0.00  | *1,016.55 F ✓        |
| 37  | 1   |          | *STEPWELL & MUDGUARD, RH nn                        | 0.00  | 0.00  | -                    |
| 38  | 1   |          | *ENTRY MUDGUARD RH OR                              | 0.00  | 0.00  | *1,443.10 F ✓        |
| 39  | 7   |          | *PAN-HEAD SCREW nec                                | 0.00  | 0.00  | 26.08 ✓ *26.11 F ✓   |
| 40  | 1   |          | *BRACKET RH X nn                                   | 0.00  | 0.00  | *409.23 F ✓          |
| 41  | 2   |          | *HEXAGON SCREW nec                                 | 0.00  | 0.00  | 40.03 ✓ *40.04 F ✓   |
| 42  | 2   |          | *WASHER nec                                        | 0.00  | 0.00  | 20.83 ✓ *20.82 F ✓   |
| 43  | 1   |          | *MUDGUARD EXTENSION RH CUT                         | 0.00  | 0.00  | *658.80 F ✓          |
| 44  | 2   |          | *GROOVED OVAL HEAD SCREW nec                       | 0.00  | 0.00  | 8.23 ✓ *8.22 F ✓     |
| 45  | 1   |          | *STEP UPPER SILVER-METALLIC MIS                    | 0.00  | 0.00  | *173.07 F ✓          |
| 46  | 1   |          | *STEP CENTRE SILVER-METALLIC MIS                   | 0.00  | 0.00  | *311.31 F ✓          |
| 47  | 8   |          | *HEXAGON SCREW nec                                 | 0.00  | 0.00  | 80.21 ✓ *80.24 F ✓   |
| 48  | 8   |          | *WASHER nec                                        | 0.00  | 0.00  | 2.65 *83.28 F ✓      |
| 49  | 8   |          | *HEXAGON NUT nec                                   | 0.00  | 0.00  | 32.90 ✓ *32.88 F ✓   |
| 50  | 1   |          | *COVER PAINTED nec                                 | 0.00  | 0.00  | *12.39 F ✓           |
| 51  | 1   |          | *STEEL BUMPER RADIATOR GUARD nn                    | 0.00  | 0.00  | -                    |
| 52  | 1   |          | *RADIATOR GUARD PAINTED BLACK X nn                 | 0.00  | 0.00  | *680.01 F ✓          |
| 53  | 1   |          | *BRACKET LH RADIATOR GUARD X nn                    | 0.00  | 0.00  | *380.29 F ✓          |
| 54  | 1   |          | *BRACKET RH RADIATOR GUARD X nn                    | 0.00  | 0.00  | *380.29 F ✓          |
| 55  | 4   |          | *HEX COLLAR BOLT X nn                              | 0.00  | 0.00  | *61.20 F ✓           |
| 56  | 2   |          | *HEX LOCK BOLT X nn                                | 0.00  | 0.00  | *21.60 F ✓           |
| 57  | 1   |          | *FLASHER LATERAL nn                                | 0.00  | 0.00  | -                    |
| 58  | 1   |          | *FLASHER LATERAL CLEAR GLASS OR (RH)               | 0.00  | 0.00  | *103.11 F ✓          |

|    |    |                                                       |      |      |               |
|----|----|-------------------------------------------------------|------|------|---------------|
| 59 | 1  | *BULB / <i>MC</i>                                     | 0.00 | 0.00 | *10.89 F ✓    |
| 60 | 4  | *PAN-HEAD SCREW / <i>MC</i>                           | 0.00 | 0.00 | *40.12 F ✓    |
| 61 | 4  | *SPEED NUT / <i>MC</i>                                | 0.00 | 0.00 | *25.20 F ✓    |
| 62 | 1  | *TURN SIGNAL, FRONT nn                                | 0.00 | 0.00 | -             |
| 63 | 1  | *AUXILIARY HEADLAMP RH, FRONT FLASHER / <i>DR</i>     | 0.00 | 0.00 | *322.56 F ✓   |
| 64 | 2  | *SLEEVE FOR HEADLAMP / <i>MIS</i>                     | 0.00 | 0.00 | *48.72 F ✓    |
| 65 | 1  | *BULB / <i>MC</i>                                     | 0.00 | 0.00 | *10.89 F ✓    |
| 66 | 2  | *OVAL-HEAD SELF-TAPPING SCREW / <i>MC</i>             | 0.00 | 0.00 | *32.22 F ✓    |
| 67 | 1  | *RD. CONNECTOR SLEEVE HOUSING 4-PIN BLACK / <i>MC</i> | 0.00 | 0.00 | *16.89 F ✓    |
| 68 | 1  | *FUEL TANK nn                                         | 0.00 | 0.00 | -             |
| 69 | 1  | *FUEL TANK X nn                                       | 0.00 | 0.00 | *3,505.50 F   |
| 70 | 1  | *SEAL Y nn                                            | 0.00 | 0.00 | *4.83 F       |
| 71 | 1  | *DRAIN PLUG X nn                                      | 0.00 | 0.00 | *30.21 F      |
| 72 | 1  | *PROTECTIVE EDGING X nn                               | 0.00 | 0.00 | *29.43 F      |
| 73 | 1  | *SIDE MARKER LIGHT WITH LIGHT EMITTING DIODE nn       | 0.00 | 0.00 | -             |
| 74 | 1  | *SIDE MARKER LIGHT X nn                               | 0.00 | 0.00 | *152.05 F     |
| 75 | 6  | *LOCKER WASHER X nn                                   | 0.00 | 0.00 | *48.30 F      |
| 76 | 2  | *LOCKER WASHER Y nn                                   | 0.00 | 0.00 | *7.92 F       |
| 77 | 1  | *DISTRIBUTOR PLUG V nn                                | 0.00 | 0.00 | *22.74 F      |
| 78 | 1  | *END PIECE X nn                                       | 0.00 | 0.00 | *15.90 F      |
| 79 | 1  | *REAR VIEW MIRROR RH DRIVE VEHICLE nn                 | 0.00 | 0.00 | -             |
| 80 | 14 | *PAN-HEAD SCREW / <i>MIS</i>                          | 0.00 | 0.00 | *37.10 F ✓    |
| 81 | 1  | *MIRROR TRIM / <i>DR MIS</i>                          | 0.00 | 0.00 | *185.35 F ✓   |
| 82 | 1  | *OUTSIDE MIRROR RH DRIVE VEHICLE DOOR / <i>DR</i>     | 0.00 | 0.00 | *2,248.44 F ✓ |
| 83 | 1  | *MIRROR TRIM RETAINER RH / <i>MIS</i>                 | 0.00 | 0.00 | *39.73 F ✓    |
| 84 | 1  | *MIRROR TRIM RH, UPPER / <i>MIS</i>                   | 0.00 | 0.00 | *50.22 F ✓    |
| 85 | 1  | *RH REAR WHEEL FLARE X nn                             | 0.00 | 0.00 | *1,700.00 F   |
| 86 | 1  | *RH REAR WHEEL FLARE SUPPORT X nn                     | 0.00 | 0.00 | *680.00 F     |

F=Franchise part.

Total Parts (\$\$) 26,807.44

Goldbell Engineering Pte Ltd/XE3031E/03/11/2022 14:51. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

15,644.58

total parts 23,173.56

# Estimates on Miscellaneous Items

| No                         | Qty | Particulars                        | Amount |
|----------------------------|-----|------------------------------------|--------|
| <u>Miscellaneous Items</u> |     |                                    |        |
| 1                          | 1   | COMPANY STICKER (DOOR) / KK (10ml) | 480.00 |
| Sub Total (\$\$)           |     |                                    | 480.00 |

# Estimates on Labour


| No                       | Particulars                                                                                 | Lab.Type | Amount   |
|--------------------------|---------------------------------------------------------------------------------------------|----------|----------|
| <u>Labour Items</u>      |                                                                                             |          |          |
| 1                        | TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC 600 X 4 | New 2400 | 4,200.00 |
| 2                        | TO TRANSFER DOOR COMPARTMENT / WINDOW GLASS / REGULATOR / LOCK / MECHANISM, ETC             | New 300  | 700.00   |
| 3                        | TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK                        | New 150  | 250.00   |
| 4                        | TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC 350 X 4                                        | New 1400 | 1,750.00 |
| Gross Labour Cost (\$\$) |                                                                                             |          | 6,900.00 |

Goldbell Engineering Pte Ltd/XE3031E/03/11/2022 14:51. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FUSO AIRMAN.

biSAFE  
STAR



SPP - Dmr RH  
- Dmr mjm RH  
- Dmr ghr RH

STEK (LKK)  
7/11/22, 1.30pm

OD- N21 AL  
Express - ?

P/P  
My BLG  
7 djs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                                 |                                    |
|---------------------------------|------------------------------------|
| Date of Submission              | 31/10/2022 15:43 (SGT)             |
| Reported by                     | Driver                             |
| Date of Accident                | 31/10/2022 11:00 (SGT)             |
| Exact Location of Accident      | AYE, Singapore                     |
| Additional Location Information | ALONG AYE TWDS TUAS BEFORE EXIT 18 |
| Country/State of Loss           | Singapore                          |

### DETAILS OF OWN VEHICLE

Vehicle Registration Number XE3031E

#### INSURED/POLICYHOLDER

|                          |                             |
|--------------------------|-----------------------------|
| Is company?              | Yes                         |
| Name Of Registered Owner | HIAP SENG TRANSPORT PTE LTD |
| Company Reg No           | 201631385R                  |
| Email Address            | sherryrt21@gmail.com        |
| Mobile Phone No          | (Phone) +65-64566093        |
| Alternative Phone No     | -                           |

#### VEHICLE PARTICULARS

|                                                                              |                    |
|------------------------------------------------------------------------------|--------------------|
| Manufacturer                                                                 | Man                |
| Model                                                                        | Tgs                |
| Variant                                                                      | -                  |
| Exact purpose for which vehicle was being used at time of accident           | -                  |
| Are you claiming under your own insurance policy for repair to your vehicle? | Yes                |
| Vehicle Category                                                             | Commercial vehicle |
| Transmission                                                                 | Manual             |
| CC                                                                           | 10518              |

#### INSURANCE COMPANY

|                                   |                                               |
|-----------------------------------|-----------------------------------------------|
| Name of Insurance Company         | China Taiping Insurance (Singapore) Pte. Ltd. |
| Policy Number / Cover Note Number | DMCVSNW00058462201                            |

#### DRIVER

|                 |                  |
|-----------------|------------------|
| Name of Driver  | ZHANG QIANGXIANG |
| Passport No/FIN | G6533091T        |
| Date Of Birth   | 21/10/1988       |
| Occupation      | Outdoor          |

|                                                                    |                                     |
|--------------------------------------------------------------------|-------------------------------------|
| Date Of Driving Pass .....                                         | 15/07/2013                          |
| Driving experience .....                                           | 9 YEARS AND 3 MONTHS                |
| Gender .....                                                       | Male                                |
| Mobile Number .....                                                | (Phone) +65-97272344                |
| Alt. Phone Number .....                                            | -                                   |
| Email Address .....                                                | sherryrt21@gmail.com                |
| Address .....                                                      | BLK 437 BT BATOK WEST AVE 5 #09-914 |
| Address complement .....                                           | -                                   |
| Postcode .....                                                     | 651437                              |
| Is the driver the policyholder? .....                              | No                                  |
| If No, Relationship of the Driver with the Insured .....           | Employee                            |
| Does Driver Own Other Vehicles? .....                              | No                                  |
| Vehicle Registration Number of Other Vehicle Owned by Driver ..... | -                                   |
| Insurance Company of Other Vehicle Owned by Driver .....           | -                                   |

#### GENERAL INFORMATION OF THE ACCIDENT

|                          |                               |
|--------------------------|-------------------------------|
| Type of Accident .....   | Collision - Change/cross lane |
| Weather Conditions ..... | Clear                         |
| Road Surface .....       | Dry                           |

#### OTHER INFORMATION

|                                                                                                           |     |
|-----------------------------------------------------------------------------------------------------------|-----|
| Was any foreign vehicle involved in the accident? .....                                                   | No  |
| Number of vehicles involved in the accident .....                                                         | 2   |
| Was anybody injured in the Accident? .....                                                                | No  |
| Was any injured conveyed to hospital by ambulance? .....                                                  | -   |
| Was any other vehicle or property damaged? .....                                                          | Yes |
| Number of Passengers (Including Driver) .....                                                             | 1   |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? ..... | No  |
| Translator's name .....                                                                                   | -   |
| Translator's ID .....                                                                                     | -   |
| Translator's phone number .....                                                                           | -   |
| Translator's email .....                                                                                  | -   |
| Original language used in the statement .....                                                             | -   |

#### DETAILS OF POLICE ACTION

|                                                 |    |
|-------------------------------------------------|----|
| Was the accident reported to the police? .....  | No |
| Was notice of intended Prosecution given? ..... | No |
| If yes, against whom? .....                     | -  |

#### CIRCUMSTANCES OF ACCIDENT

ON 31/10/2022 AT ABOUT 1100HRS.I WAS DRIVING ALONG PIE TWDS TUAS BEFORE EXIT 18. VEHICLE IN FRONT OF ME JAMMED, I JAMMED BRAKE ALSO, DUE TO THE SUDDEN BRAKE, MY VEHICLE SLIGHTLY SWERVED TO THE RIGHT AND COLLIDED WITH VEHICLE B.

#### ATTACHMENT(S)

|                                                     |     |
|-----------------------------------------------------|-----|
| Are accident photos available for attachment? ..... | Yes |
| Was there any video captured by Car Camera? .....   | No  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                   |                    |
|-----------------------------------|--------------------|
| Vehicle Registration Number ..... | XE4024U            |
| Vehicle Manufacturer .....        | -                  |
| Vehicle Model .....               | -                  |
| Vehicle Variant .....             | -                  |
| Vehicle Colour .....              | -                  |
| Vehicle Category .....            | Commercial vehicle |

|                                               |                      |
|-----------------------------------------------|----------------------|
| Name of Driver .....                          | MUTHU ANBARASU       |
| Passport No/FIN .....                         | G7946572R            |
| Contact Number .....                          | (Phone) +65-98954779 |
| Address .....                                 | -                    |
| Address complement .....                      | -                    |
| Postcode .....                                | -                    |
| Insurance Company Name .....                  | -                    |
| Nature Of Damage .....                        | -                    |
| Details of property damaged in accident ..... | -                    |
| No. Of Passenger (Including Driver) .....     | -                    |

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



A: XE30316

B: 784084U

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 3/10/2023 at about 11:00hrs. I was driving along AYE towards Tuas before Exit 18.

Vehicle in front of me jammed brake, I jammed brake also, due to the sudden

brake, my vehicle slightly swerved to the right and collided with vehicle B.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**中国太平**  
CHINA TAIPING

**中国太平保险(新加坡)有限公司**  
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Motor Commercial

MZ301/C

R SN

AN0698A

Cov. Type C

**CERTIFICATE OF INSURANCE**  
Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)  
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1967  
Road Transport Act, 1987 (Malaysia)  
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No.

DMCVSNW0058462201

Engine No: 50547181714720

Cha. No. WMA26SZZ9-M742151

1. Index Mark and Registration  
Number of Vehicle

XE3031E

AUTOSAFE  
\*\*\*\*\*

2. Name of Policy Holder

HIAP SENG TRANSPORT PTE. LTD.

3. Effective date of the Commencement of  
Insurance for the purposes of the Regulations,  
Ordinance or Enactment

06/06/2022  
(00.00.00)

Excess Sect 1. \$12,000.00  
EX ON WINDSCREEN. \$100.00

4. Date of Expiry of Insurance

05/06/2023

5. Persons or Classes of Persons entitled to drive\*

- (1) Whilst the vehicle is being used in connection with the Policyholder's business  
Any person provided he is in the Policyholder's employ and is driving on their order or with their permission.  
(2) Whilst the vehicle is being used for social, domestic or pleasure purposes  
Any person who is driving on the Policyholder's order or with their permission.  
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use\*

- (1) Use in connection with the Policyholder's business.  
(2) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.  
(3) Use for social, domestic or pleasure purposes.

The Policy does not cover

- (1) Use for racing, pace-making, reliability trial or speed-testing.  
(2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.  
(3) Use for the carriage of passengers for hire or reward.

HIRE PURCHASE CO.: SINGAPURA FINANCE LTD

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

**I/We hereby Certify** that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By: **RVO & ASSOCIATES PTE LTD**  
Authorised Officer

Authorised Signatory

China Taiping Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200208354E)  
3 Anson Road #16-00 Springleaf Tower Singapore 079909

☎ 6389 6111

☎ 6222 1033

🌐 www.sg.cntaiping.com