

ASS. REC. BY:

REF: FOZ/22011102/KAY3

C

Kennerth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/LWS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop n/s Liam Tan

of 003C

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 841K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKK 46520 Yr Regn: 07, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A) Wagon

Make: Audi Q5 c.c. 1984

Colour: M. Blade A/C: Insured / Std / Nil / NA

Sp. Reading: 65220 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: W A U 7 7 7 8 R 8 0 A 1 0 1 3 7 0

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / SIRIm / STD ATRIm or

Tyre Size: F: 235/55R19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 12/10/22

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>Got BZ</u>

17/11 61 Pm @ 2300h Caber (Red, 4581.03, 67%)

Date/Time, File Pass to? : Prell. Report : Final Report

Date/Time, File Return to? _____

Days Of Repair: 4
Resurvey No. of Trlp: 1

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:	
Transportation:	
S - RS. St	
Exp. Ins	
Others	
TOTAL	

Report Format : _____
Lump Sum / I.B.I: (\$) 2300

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 003C

Vehicle Details

Vehicle No.: SKK4652D
Vehicle to be Exported: Yes
Intended Deregistration Date: 01 Nov 2022
Vehicle Make: AUDI
Vehicle Model: Q5 2.0 TFSI QU (PI)
Primary Colour: Black
Manufacturing Year: 2013
Engine No.: CNC016261
Chassis No.: WAUZZZ8R8DA101370
Maximum Power Output: 165.0 kW (221 bhp)
Open Market Value: \$44,552.00
Original Registration Date: 19 Jul 2013
First Registration Date: 19 Jul 2013
Transfer Count: 1
Actual ARF Paid: \$54,373.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 18 Jul 2023
PARF Rebate Amount: \$27,186.00

Intended COE Rebate Details

COE Expiry Date: 18 Jul 2023
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$77,000.00
COE Rebate Amount: \$5,485.00
Total Rebate Amount: \$32,671.00

The information contained herein is correct as at 01 Nov 2022

OK

Not Withoin
 11 Sep @ 2300h
 Resurvey After Paint
 4 days



ESTIMATE TO REPAIR

SURVEYOR NAME	:	
DATE OF SURVEY	:	
TIME OF SURVEY	:	

VEHICLE NO. : SKK 4652 D
 MAKE : AUDI
 MODEL : Q5 2.0 TFSI
 YEAR : 2013
 CHASSIS NO : WAUZZZ8R8DA101370

DATE : 14-Oct-22
 DATE OF ACCIDENT : 12-Oct-22
 THIRD PARTY REF : SBS 6468 X
 THIRD PARTY REF : SBS TRANSIT LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1pc	rear bumper				\$ 1,135.90
1pc	rear bumper reinforcement				\$ 458.65
1pc	tail gate				\$ 3,270.15
1pc	tail gate lamp <i>885</i>				\$ 1,109.30
1pc	Q5 emblem				\$ 72.30
1pc	2.of emblem				\$ 72.30
1pc	centre emblem				\$ 93.65
	Less 10%				\$ 6,212.25
					\$ 621.23
					\$ 5,591.03
1pc	rear windscreen sealant	S.Nett			\$ 40.00
	To putty & spray paint				\$ 600.00
	To remove & transfer rear windscreen glass				\$ 120.00
	To transfer tail gate fitting.				\$ 80.00
	Labour Charges				\$ 450.00
TG/VL	TOTAL				\$ 6,881.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: