

ASS. REC BY: TaufikREF: ca/TM/22011134/743

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WRDate: _____ Person Contacted: Amay Vehicle: IN / OUTVeh No: SNC86514Yr Regn: 2016, March

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 140C.C. 1685Colour Blue

A/C: Insured / Std / NI / NA

Sp. Reading 888541

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MMHCB414464085760

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 8/11/22Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufikh confirmed lump sum: \$1100 and 2 days
(red, \$875.98, 44%)

Date/Time, File Pass to?



: Preli. Report

1) 27/12/22

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 2Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Report Format: TPLump Sum / I.B.A. / 1100

Add Fee:



: Site Insp (\$ _____)



: Interview (\$ _____)



: Tech. Invs (\$ _____)



: Weekend (\$ _____)

S + RS \$ _____

Photos

Others

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)

CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	06/11/2022
Vehicle Reg. No.:	SHC8651H	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Vehicle Reg. Date:	17/03/2016
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4FDFU596620	Chassis No:	KMHLB41UMGU085760
Odometer:	888541 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	1,154.98
Miscellaneous Items	11.00
Labour	810.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,975.98
+ GST 7.00% (S\$)	138.32
Nett Amount (S\$)	2,114.30

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 07 Nov 2022)**Parts:** 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC8651H/07/11/2022 11:13**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	de ✓ *553.00 FL
2	1		*REAR BUMPER LOWER COVER	20.00	0.00	de ✓ *228.00 FL
3	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	un X ✓ *428.40 FL
4	1		*REAR BUMPER CLIPS	20.00	0.00	un ✓ *2.20 FL 22
5	1		*REAR BUMPER MAT	0	0.00	un ✓ *50.00 FS
6	1		*REAR BUMPER REVERSE SENSOR	0	0.00	un ✓ *135.70 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 1,397.30**- List Item Discount on L Items (\$\$)** 242.32**Total Parts (\$\$)** 1,154.98

ComfortDelGro Engineering Pte Ltd/SHC8651H/07/11/2022 11:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

803
20% - 642.40
SN 185.70

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	280 450.00
2	SPRAY PAINTING	New	250 300.00
3	REMOVE/ REFIX REVERSE SENSOR	New	30 60.00
Gross Labour Cost (S\$)			560 810.00

ComfortDelGro Engineering Pte Ltd/SHC8651H/07/11/2022 11:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanjin 97495749
WP 8/11/22 1pm
2 days
LIS history after report
tanjin@kanto.com

642.40
185.70
11
560
1399.10
459/1100
2 days
X

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5174199

JC NO:305535633

STOMER
/MS COMFORT TRANSPORTATION PTE LTD
STOMER NO. 7010045
DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (R) (O)
(P)
COUNT CARD NO.


REGN NO. SHC8651H	MILEAGE
MAKE HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 07.11.2022 09:10
YR OF MANU. 17.03.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU085760	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 06.11.2022
NATURE: 3P 06.11.2022

S/NO LABOR CODE

DESCRIPTION



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

No.: SHC8651H CHIANG

Vehicle No.: SHC8651H

if Service Advisor

Signature/Date

Name of Service Advisor

Date

eturned to Service Reception upon collection

To be kept by Security Guard