1)

ASS. REC. BY:	cs/jes 22011136/1		2245	
	ASSIGNMEN		1	
From: Date:	Veh No:	SMT 7737	C Yr Regn: 266 1 MAY	
Estimated Cost:			Lorry / Taxi / Prime Mover /	
OD TP / WS / TP RES / OD RES / EVA / INV / M	<u></u> Truck	/ Trailer or		
To Inspect Vehicle No: SMT 7737C	Make:	Homoa odyssey	2.4EXUS 8/Fec 2356	
at Workshop m/s VIN) mo TVR	Colour	WHITE "	A/C: Insured / Std / NI / NA	
of 160, SIN MILM DR \$08-	Sp.Reading	174618	T/Radio: Insured / Std / NI / NA	
Insured: ECICS	Eng/No:			
Policy No.	C/No:	JHMRL189	046204187	
Claims No.	Gen. Cond: 0	Good (Fair Poor / Bu	mt	
Sum Insured: Excess:	TBA Steering: (no	rder / Jammed / Leake	d/Burnt or	
(Client's Record)	Brake: Jno	rder / Jammed / Leake	d/Burnt or	
Make of Veh:	0	I STD A/Rim		
	Tyre Size:		5 45 8 8	
(Policy Condition)	1,700 0.20.	R: 20	2 (4) (10	
Remark: The veh had commenced its	N/S O/S RS / NIN / F		A / MIC / OHTSU / PIR / SUMI /	
repair at the time of inspection.	TOYO / YO		A / MIC / URI SU / PIK / SUMI!	
Bal. or Market Value: &SK			_	
IDAC Accident Rport: Consistent? : Ye	Front P/Pal	1	Rear	
0.6 8 2046	-	7 mm	R/Bal	
AND THE RESERVE OF THE PARTY OF		6 mm	L/Bal. 6 mn	
Est. Repairs: days Res.: Ye			D.O.I. 68/11/22	
Lum Sum: % 3 Val.: Ye	s or No Survey held a	tVIN	fmotor.	
CA / REV / REP. / 24 HRS	Des. of Dama	ges: Frt Kear / O/S	I N/S / U/C / Rooftop or	
Date: Person Contacted:	Vehicle: IN / OUT			
- John Obiliadios.	The U/C	Chassis frame / Bo	dy Structure affected due to collisio	
Date / Time Action / Instruction REPAIR LIMIT - 441		The second secon		
POPSILE LIMITY TT				
h				
	**************************************		M11	
: Preli. Report	Dave Of Box	Days Of Repair:		
: Final Report				
Time, File Return to?	Resurvey No	o of Trip:	Survey Fee:	
editorioscopies and MET (MET 1 A A SETECT)			Transportation:	

: Interview (\$) Photos Report Format : Tech. Invs (\$ Others Lump Sum / I.B.I: (\$ Weekend (\$

Add Fee:

:Site Insp (\$

TOTAL

)__S+RS__SI

Vin's Motor Pte Ltd 160 Sin Ming Drive #03-03 Sin Ming Autocity Singapore 575722 Tel: 6453 2121 Fax: 6459 9795 GST Registration No. 199906067G



Estimated Cost of Repair

Attention To

ECICS LIMITED

Claim Details
Case Ref. No.

7 Temasek Boulevard

: OD/112022/5754

· F

#10-01 Suntec Tower One

Date : 05-11-2022

Singapore 038987

Accident Date : 03-11-2022

Vehicle Details

Make & Model :

Honda ODYSSEY 2.4 EXV-S CVT

SR

Chassis No

JHMRC1890GC204187

Registration No : SMT7737C

S/N	Description	Qty	Amount (S\$)
	TAILGATE Y	1.00	\$820.00
2	TAILGATE GLASS RH MOULDING	1.00	\$30.00
3	TAILGATE GLASS LH MOULDING M	1.00	\$30.00
4	TAILGATE GLASS TOP MOULDING	2.00	\$60.00
5	TAILGATE GLASS SIDE MOULDING M	2.00	\$80.00
6	TAILGATE EMBLEM 44	1.00	\$40.00
7	TAILGATE CENTRE REFLECTOR CONT.	1.00	\$160.00
3	TAILGATE RH REFLECTOR CA	1.00	\$280.00
9	TAILGATE LH REFLECTTOR CA	1.00	\$280.00
10	TAILGATE LOWER CHROME MOULDING .	1.00	\$110.00
1	TAILGATE INNER TRIMBOARD 3.44	1.00	\$180.00
2	TAILGATE REVERSE CAMERA	1.00	\$420.00
3	TAILGATE INNER LOCK CON	1.00	\$110.00
4	TAILGATE RUBBER ~~ /	1.00	\$80.00
5	REAR BUMPER de/	1.00	\$480.00
5	REAR BUMPER PARKING SENSOR	2.00	\$448.00 3
	REAR BUMPER RH SIDE RETAINER X	1.00	\$20.00
	REAR BUMPER LH SIDE RETAINER 🗡	1.00	\$20.00
	REAR BUMPER CLIPS *	10.00	\$20.00
l	REAR END PANEL FOR	1.00	\$350.00
			\$4,010.00
		Margin: 10%	\$401.00
	WINDSCREEN GUM ~~	1.00	\$4,411.00 \$86.00
	TO REMOVE AND REFIX TAILGATE GLASS ~	1.00	\$180.00
	TO REPAIR DAMAGES		\$680.00
	TO SPRAY PAINTING (PEARL)	1.00	
	. S. ISTI PARTING (FEARL)	1.00	\$890.00



Vin's Motor Pte Ltd 160 Sin Ming Drive #03-03 Sin Ming Autocity Singapore 575722 Tel: 6453 2121 Fax: 6459 9795 GST Registration No. 199906067G

Subtotal w/o GST:

\$6,231.00

Rasue
He 90010068

Sdays
He PP

08/11/22 @ 13 45

EXCESS: TRA

Recent

Reson after report
before point

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

SV1022B50002 / Vin's Motor Pte Ltd [575722] ENTRY DATE & TIME: 05/11/2022 13:38 (SGT) SUBMITTED BY: Raymond Teo Yun Loong VERSION: 1 (05/11/2022 13:38 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

- 2. This Form must be completed by the Policyholder and/or the Actual Driver
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Reported by

Date of Accident

Exact Location of Accident

Additional Location Information

Country/State of Loss

05/11/2022 13:38 (SGT)

Both

03/11/2022 18:00 (SGT)

Singapore

NEWTON 1 CONDO BASEMENT CARPARK

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SMT7737C

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

NRIC No

Email Address

Mobile Phone No

Alternative Phone No

SHARON DOMINIQUE KHONG SWEE AI

SXXXX559I

SHARONDOMINIQUE@HOTMAIL.COM

(Phone) +65-90468382

VEHICLE PARTICULARS

Manufacturer

Model Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category

Transmission

CC

Honda

ODYSSEY 2.4 EXV-S CVT SR

Private use

Yes

Private car

Auto

2356

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

ECICS Limited MPC22P00110300

DRIVER

Name of Driver

NRIC No

Date Of Birth

Occupation

SHARON DOMINIQUE KHONG SWEE AI SXXXX5591

18/07/1977

Indoor



23/04/2003 **Date Of Driving Pass** 19 YEARS AND 7 MONTHS Driving experience Female Gender (Phone) +65-90468382 Mobile Number Alt. Phone Number SHARONDOMINIQUE@HOTMAIL.COM **Email Address** BLK 1 NEWTON ROAD #14-02 Address Address complement 307943 Postcode Yes Is the driver the policyholder? If No, Relationship of the Driver with the Insured No Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Collided into Property Type of Accident Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) No soliciting/offering accident claims assistance? Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement

PASSENGER 1

SON Name Gender Male

DETAILS OF POLICE ACTION

Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Yes No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number **PILLAR** Vehicle Manufacturer Vehicle Model Vehicle Variant

Vehicle Colour
Vehicle Category
Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

NA / Unknown

SKETCH PLAN

IMPORTANT NOTICE

- * Please report garrestly the actails of the accident to speed up the claims process
- This Plans must be organized by the Probyholded areting the Agual Direct
- Standard placetar in the company of the large of the property of the contract of
- Any take reporting may be referred to the Traffic Police Department for investigation

The second of th

1. Surscreampenthy Person (1 Data Protection Act (PDPA))

The end of acceptant of the end of the constraint of the Month Language with a several constraint of the end o

Class S. M. C. S. M. W. C. S. My with recommendation and the classical decreases upon in Math. Phys. 68 (1994) 1997.

The Automotive Street Control of the Landers

And the first sequence of two safety and sequence is a sequence of the first sequence of the firs

(iii) independent and indicate the residual consequence is taken pelos as encountries and some some some conditions of the condition of the solution of the active and the solution of the condition of the con

and the first of the control of the parties was become what the time that the

Demonstrate Furper of

do for an except have insured whose it was accordent and the lessons to appropriate the property of the order of the extra property of the restoration of the state of the extra property and

sing Permit (Primar) in a plant and the Liby my of the foreigner once to Aris magnet perfect projection on speciment gives a west favour or in the decidence of Strynopper trace or more of the above Purposes.

Dogii

for hithward Systems for its state-

"Whitshot by Report in Centre Responds (Name as in NRIQAD and



Describe Circumstance of the Accident

At around 6pm on 3 November 2027, I was
reversing out of my partiting lot and the
rear of my vehicle, SNT 7737- which against
coused
the carpore pillar The damage was at the

Decreation

Muca

A CONTROL OF THE PROPERTY OF T

Spoi

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

/ehicle Owner Particulars	The state of the s	URNIENO.
Owner ID Type:	Singapore NRIC	~~~~~~
Owner ID: Vehicle Details	5591	
Vehicle No.:	SMT7737C	*****
Vehicle to be Exported:	No	
Intended Deregistration Date:	07 Nov 2022	
Vehicle Make:	HONDA	*****
Vehide Model:	ODYSSEY 2.4 EXV-S CVT SR	
Primary Colour:	White	
Manufacturing Year:	2016	
Engine No.:	K24W72011955	
Chassis No.:	JHMRC1890GC204187	
Maximum Power Output:	129.0 kW (172 bhp)	
Open Market Value:	\$29,939.00	
Original Registration Date:	23 May 2016	
First Registration Date:	23 May 2016	
Transfer Count:	1	
Actual ARF Paid: Intended PARF Rebate Details	\$33,915.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	22 May 2026	an dayores
PARF Rebate Amount: Intended COE Rebate Details	\$22,044.00	
COE Expiry Date:	22 May 2026	
COE Category:	B - Car above 1600cc or 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$51,010.00	-
COE Rebate Amount:	\$18,059.00	
Total Rebate Amount:	\$40,103.00	

The information contained herein is correct as at 05 Nov 2022

Honda Odyssey 2.4A EXV-S Sunroof

Overview

Financial

Accessories

Similar

Research

Photos

Мар



Price	\$86,880		
Depreciation ①	\$19,620 /yr View models with similar depre	Reg Date	02-Jun-2016 (3yrs 6mths 24days COE left)
Mileage	107,300 km (16.7k /yr)	Manufactured ②	2016
Road Tax	\$1,630 /yr	Transmission	Auto
Dereg Value (3)	\$40,227 as of today (change)	OMV ()	\$29,939
COE	\$51,010	ARF (2) Part or this list of	\$33,915
		Power as sale po 25 on 40 on 4	129.0 kW (172 bhp)
Curb Weight	1,855.kg	No. of Owners	