

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	08/11/2022 11:31 (SGT)
Reported by	Driver
Date of Accident	05/11/2022 16:25 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	VIVO CITY CAR PARK
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJV8277G

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ROHIT KUMAR VERMA
NRIC No	SXXXX579Z
Email Address	ROHIT_K_R@YAHOO.COM
Mobile Phone No	(Phone) +65-83223842
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	A180
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1595

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	2070005946-02

DRIVER

Name of Driver	SHIPRA VERMA
NRIC No	SXXXX177C
Date Of Birth	18/09/1982
Occupation	Indoor

Date Of Driving Pass	01/08/2009
Driving experience	13 YEARS AND 3 MONTHS
Gender	Female
Mobile Number	(Phone) +65-98550970
Alt. Phone Number	-
Email Address	NO@EMAIL.COM
Address	186 DEPOT ROAD #21-12 THE INTERLACE
Address complement	-
Postcode	109687
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	UNKNOWN
Gender	Female

PASSENGER 2

Name	UNKNOWN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

MR CAR WAS GOING STRAIGHT AND CAR 'B' SUDDENLY KNOCKED INTO RIGHT SIDE OF MY CAR. CAR 'B' DID NOT STOP AT THE STOP LINE.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE6128B
Vehicle Manufacturer	Mercedes
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	TAN KIM POH
Passport No/FIN	SXXXX971G
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	Lonpac Insurance Bhd
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Lor


Shepa Vene

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

My Car was going straight and Car "B"
Suddenly knocked into right side of my car.
Car "B" did not stop at the stop line.

Declaration

We declare the foregoing particulars are true in every respect.

Shipre Vene

Policyholder's Signature / Date & Time

Shipre Vene

Driver's Signature (if driver is not the policyholder) / Date & Time

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Lor

Witnessed by Reporting Centre Personnel



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJV8277G

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information	
WIP No	60757
Reg No/Reg Date	SJV8277G / 20/01/2020
Date In/Mileage	/ 23431
Chassis No	WDC1569422J6863190
Engine No	27091031944568
Make/Model	MB/GLA 180 SPORT UTILITY VEH
Colour/Trim	026 667 Demin Blue / 043 381 ARTICO/FabB

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	08/11/2022/ 14:17	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
THIS IS NOT AN OFFICIAL TAX INVOICE				
Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : 2070005946-02 // 5-11-2022 DRIVE IN/TP VEH NUMBER : 5-11-2022 // GBE6128B - LONPAC DATE IN/DATE SURVEY: DIRECT SETTLEMENT BY:				2400.00
A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				1800.00
A BPIRES RESPRAY FRONT BUMPER & RH/FRONT FENDER			0.10	380.00
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				120.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT				540.00
A BPILAB TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT				60.00
S BPNSUB LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT) WHEEL BALANCE AND INSTALL NEW VALVE HEAD				240.00
A 54099101 EXTRA WORK TO PROGRAM AND CODE HEADLAMP CONTROL UNIT(AFTER QUICK TEST)				180.00
A 97250001 CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM	1.00	1430.59	00.00	1430.59
M FRONT BUMPER	1.00	67.92	00.00	67.92
M FRONT BUMPER MB EMBLEM	1.00	66.06	00.00	66.06
M RH/SIDE INNER COVER BRACKET	1.00	72.63	00.00	72.63
M RH/SIDE COVER BUMPER AREA	1.00	195.43	00.00	195.43
M OUTER DISTANCE SENSOR	6.00	7.10	00.00	42.60
M SPACER RING	1.00	984.80	00.00	984.80
M CTR/SILVER COVER BUMPER AREA	1.00	164.77	00.00	164.77
M RH/SIDE BOTTOM BLACK TRIM BUMPER				

Confirmed & accepted by

Authorized signatory and company stamp

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan-go@cyclocarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJV8277G

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No **60757**
Reg No/Reg Date **SJV8277G / 20/01/2020**
Date In/Mileage **/ 23431**
Chassis No **WDC1569422J6863190**
Engine No **27091031944568**
Make/Model **MB/GLA 180 SPORT UTILITY VEH**
Colour/Trim **026 667 Demin Blue / 043 381 ARTICO/FabB**

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	08/11/2022/ 14:17	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M TOP BASIC MOUNTING FOR BUMPER	1.00	211.54	00.00	211.54
M RH/FRONT FENDER	1.00	910.28	00.00	910.28
M RH/COVER FENDER & BUMPER AREA	1.00	225.49	00.00	225.49
M RH/FRONT FENDER BRACKET	1.00	13.54	00.00	13.54
M RH/WHEEL ARCH COVER	1.00	191.69	00.00	191.69
M EXPANSION RIVET	6.00	6.09	00.00	36.54
M CROSS MEMBER	1.00	350.27	00.00	350.27
M RH/FRONT BUMPER SUPPORT	1.00	17.09	00.00	17.09
M RIGHT HEADLAMP UNIT	1.00	2653.89	00.00	2653.89
M LIGHT RANGE CONTROL UNIT	1.00	788.90	00.00	788.90
M RH/FRONT DISK WHEEL	1.00	720.24	00.00	720.24

THIS IS NOT AN OFFICIAL TAX INVOICE
ESTIMATE

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre Pandan Loop

Confirmed & accepted by	Nett	14,864.27
	7% GST on 14864.27	1040.50
	Total Payable	15,904.77

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg