

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD	R	Ref:	CS/INC22011172/Sqy3q2	
	75 BRAS BASAH R INCOME CENTRES	ROAD SINGAPORE 189557	D	Date:	01/12/2022	
	ATTN: JEFF LIN		C	Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLD 7982G	Veh. Inspected		SLQ 8767L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1196006- 002	Excess (\$)		0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		08/11/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA VEZEL	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	RU31230386	Colour		BLACK	
	Odometer	362406 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	FARROAD		6 mm	
	L/H Front Tyre	215/60 R16	FARROAD		6 mm	
	R/H Rear Tyre	215/60 R16	FARROAD		6 mm	
	L/H Rear Tyre	215/60 R16	FARROAD		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	06/11/2022	Inspect Date / Ti	me	08/11/2022 (05:28 PM)	
	Survey held at	TEAMWORK GARAGE PTE LTD)			
		53 UBI AVENUE 1 #01-24				
		SINGAPORE 408934.				
5a.	. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	STIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				