

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	INCOME INSURAN	ICE LTD	Ref:	CS/INC22011173/Twy3m4	
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557	Date	e: 17/03/2023	
	ATTN: ENG HUEY	HUEY	Cod	e: INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBL 18M	Veh. Inspected	SKZ 8163T	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1195623-002	Excess (\$)	0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	08/11/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA WISH	c.c	1797	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	ZGE206024339	Colour	BLACK	
	Odometer	111271 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/40 R18	BRIDGESTONE	6 mm	
	L/H Front Tyre	225/40 R18	BRIDGESTONE	6 mm	
	R/H Rear Tyre	225/40 R18	BRIDGESTONE	6 mm	
	L/H Rear Tyre	225/40 R18	BRIDGESTONE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
	DAMAGES SEE DI	ETAILS.			
_					
5.	General Information				
	Accident Date	04/11/2022	Inspect Date / Time	09/11/2022 ( 10:30 AM )	
	Survey held at	AUTOBACS CAR CARE (S) PTE LTD			
		8 KAKI BUKIT AVENUE 4 #08-40/45/46 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days			