AS RECOBY: Steve	
The state of the s	GNMENT .
From: Date:	Veh No: SMH 85117 Yr Regn: 12/0/19
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD TP WS ITP RES I OD RES I EVA I INV I MV	Truck / Trailer or
To Inspect Vehicle No:	Make: RMW 5001 c.c 1998
at Workshop m/s	Colour BINC A/C: Insured / Std / NI / NA
01	Sp.ReadingT/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CNO: WRASAI2030R) 184
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Modi: Nii / SIRim / STD A/Rim or
Make of Veh:	ALT ILL PIE
(Policy Condition) Remark: The yeb had commenced its N/S O/S	BS I DUN I EXNOVA I SY I FS I LIZA I MIC I OHTSU I PIR I SUMI I
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 5 mm R/Bal. 5 mm
GIA / PR Seen: Consistent? : Yes or No	UBal. 5 mm UBal. 5 mm
Est Repairs: days Res.: Yes or No	0.0A 6/11/72 D.O.I. 9/11/21
Lum Sum: % 3 Val.: Yes or No	Survey held at Performonce
CA / REV / REP. / 24 HRS	Des. of Damages: Frt I Rear I O/S I N/S I U/C I Rooftop or
Vehicle: IN/OU	Front RY
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
1/1/2/04/	
· Jan	
Osle/Time, File Pass to? : Preli. Report	Days Of Repair:
: Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	
2) Add	Fee: : Site Insp (\$)8 + R\$\$I
	: Tech, Invs (\$) Others
Ropert Formel: Lump Sum (LB): (\$\frac{1}{2}\$: Weel and (\$
Emity court to a co	TOTAL
	· · · · · · · · · · · · · · · · · · ·
7. NO.	ng ringge debut g
	र विकास क्रम् ्रः - १९८१ - १९८४ - १९८४ - १९८४ - १९८४ - १९८४ - १९८४ - १९८४ - १९८४ - १९८४ - १९८४ - १९८४ - १९८४ - १९८४ - १९८४ - १९

Dealer

Performance Motors Limited

A Sime Darby Notore Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 189941 Fax. 64747770 280, Eampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773)15, Alexandra Road Sime Darby Business Centre Singapore 159944 Pax. 64796601 (AfterSale 4796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

0 8 NOV 2022

Page No. : 1 of 5

Estimate No.	:	b1	63937
Date Estimated	:	07/1	1/2022

Singapore 730402

Prepared By : Foong Shiuh Jye

- ESTIMATE REPAIR FOR - Joshua Chew Shu Heng Blk 402 Woodlands St 41 #06-134	- ACCOUNT - 135 China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
REGN. NO.	CIMEDID NO.			19513
SMH8511T	WBAJA12030BJ20879	12/02/2019	520i	19513

SMH8511T	WBAJA12030BJ20879 12/02/20	19	520i	*-	19513	
	DESCRIPTION To replace bumper front panel, front right side par attachments	nel and	front	_	1700	VALUE 3,400.00
	To spray paint bumper front panel and front right s	side par	nel		1826	1,923.00
	To replace right headlight.				431	481.00
	To carry out body cavity preservation. (Per panel).				112	118.00
	To check steering geometry and conduct wheel at accordance with BMW specifications. (1x).	lignmen	t ira		5 04	531.00
	To check electrical wiring system at the front secti for proper function including adjustment of headlig	ion ghts.			168	177.00
	To remove old PDC assembly, replace damaged preconnect to new bumper including conduct check proper function.	parts an k for	d		168	177.00
	Sundries.					150.00
				Total Labour 1:	-	6,957.00
	DESCRIPTION FRT RH SIDE PANEL ALUMINIUM / 00			OTY PRIC 1 952.05		VALUE 952.05
	COVER GRILLE RH (1). RH GRILLE AIR INLET OPEN (LINES)	CUT (M		1 77.75 1 118.75 1 70.20		77.75 118.75 70.20
	IMPACT ABSORBER TOP ()			1 76.15 1 758.85		76.15 758.85
	FRT BUMPER PANEL PRIMED (PMA/PDC) / FRT BUMPER TOW HOOK COVER X SET MOUNTING PDC/PMA SENSOR FRT /	M		1 1,454.15 1 53.70 1 80.55		1,454.15 53.70 80.55
	TRIM GRILLE FRT (I CAM) RH HEADLIGHT LED AHL HIGH (ICON LIG	- RI	2	1 25.90 1 4,960.90		25.90 4,960.90


Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770 280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 (AfterSa 64796624 (Motorra

(AfterSales) (Motorrad)



ESTIMATE

Estimate No.

: b1 63937

Date Estimated

: 07/11/2022

prepared By

Foong Shiuh Jye

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SMH8511T

WBAJA12030BJ20879

12/02/2019

520i

19513

Page No. : 2 of 5

DESCRIPTION

ULTRASONIC SENSOR IMPERIALBLAU (WA8

PRIC 373.90 VALUE 373.90

Total Parts

9,002.85

Steve (LKK) 9/11/72, 3.00ps

MIL MAN PREMY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurve to 1 and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1 Parts

:

6,957.00 9,002.85

0.00

0.00

Labour 2 Excess

Total GST @ 7%

1,117.19

Grand Total

17,077.04

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

POX22B70007 / Performance Motors Limited SPOX22B70007 / Performance Motors Limited SPOX22B70007 / Performance Motors Limited NTRY DATE & TIME: 07/11/2022 14:40 (SGT) SUBNITTED BY: Peh Ah Hoon SUBNITTED BY: Peh Ah Hoon SUBNITTED BY: Peh Ah Hoon SUBNITTED BY: Peh Ah Hoon



SINGAPORE ACCIDENT STATEMENT

MPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate. 3. Information provided must be as truthrul and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudial policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving of this report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Reported by Date of Accident **Exact Location of Accident** Additional Location Information 07/11/2022 14:40 (SGT) Driver 06/11/2022 09:00 (SGT) Singapore

BLK 406A WOODLANDS STREET 41

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SMH8511T

INSURED/POLICYHOLDER

Country/State of Loss

Is company? Name Of Registered Owner NRIC No Email Address Mobile Phone No

No JOSHUA CHEW SHU HENG SXXXX193F joshuachewsh@gmail.com (Phone) +65-96633827

VEHICLE PARTICULARS

Alternative Phone No

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category Transmission

CC

Private use

BMW

520:

No - Claiming third party

Private car Auto 1998

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number Liberty Insurance Pte Ltd SD22V05777

DRIVER

Name of Driver NRIC No Date Of Birth

CHAN BIK LAI SXXXX199D 21/09/1961

Accident report SP0X22B70007

Page 1 of 23



Of Driving Pass

Of Driving Pass

Of Driving experience

Path of the Number

Alt. Phone Number

Alt. Phone Number

Alt. Address

Address

Address

Address

Address complement

Postcode

Is the driver the policyholder?

Is the driver Own Other Vehicles?

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

29/03/1985
37 YEARS AND 8 MONTHS
Female
(Phone) +65-96633827
joshuachewsh@gmail.com
402 WOODLANDS STREET 41 #06-134
730402
No
Parent
No

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface Hit and run / Vandalism / Damaged whilst parked Clear Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other vehicle or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s)
soliciting/offering accident claims assistance?
Translator's name
Translator's phone number
Translator's email
Original language used in the statement

No
2
No
Yes
1
No
-

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Was notice of intended Prosecution given?
If yes, against whom?

No No

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACH

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Yes No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Manufacturer Vehicle Wodel Vehicle Variant Vehicle Colour Vehicle Category Name of Driver Passport No/FIN

PA5337B

:

Goods vehicle

LAKSHMANAN PALANIKUMAR

CAAAAdust

C Accident report SP0X22B70007

Page 2 of 23



Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

(Phone) +65-85253652
China Taiping Insurance (Singapore) Pte. Ltd.





SKETCH PLAN

Le gry (kun	nar) hitted my park	ed car at the Car
ark.	,	
	The second secon	grade and the same direct transfer for the same
	and the second	
	The second secon	
	The second secon	The second secon
	and the second s	and the state of t
		the second
CLARATION	The second secon	THE THE RESIDENCE CONTROL OF THE PARTY OF TH
e declare the foregoing part	iculars are true in every respect	
	A	Foong Shiuh Jye regormance Motors Limited 303 Alexandra Road
	3	Sime Darby Berformance Ges
uyhorden's Signature le & Timbe	Oriver's bigrature (It privet is not the policyholder)	Sime Daily Fortormance Gos Name Singapore 1599 Posture
HUA OFFW SILL HARY	to entere of contains handly activity	NR C/I N No .