Resurvey No. of Trip: : Preli. Report Obleiffine, File Pass to? Transportations : Final Report . : Sife Insp (\$ Date/Time, File Return to? Add Fee! Intarview (\$ 2) 18/1/23-typist Tech, Invs (9 Weekend (\$ Merimen Report Connect: Lump 3181 / \$9086.95

Days Of Repair:

Survey Fee:

, Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

The information contained herein is correct as at 03 Nov 2022

Singapore NRIC

575C

SNH4369C

Yes

03 Nov 2022

TOYOTA

RAIZE 1.2X CVT

White

2022

WA0038625

A201A0003468

64.0 kW (85 bhp)

\$15,173.00

27 Oct 2022

27 Oct 2022

\$15,173.00

Yes

26 Oct 2032

\$11,379.00

26 Oct 2032

A - Car-Details at OneMotoring

\$87,889.00

\$70,311.00

\$81,690.00

OK

Goldbell Engineering Pte Ltd 8 Tuas Ave 18, Singapore 638892

Insurer Reference: SNH4369C Repairer Reference: 054235

Date calculated: 07/11/2022 3:13 PM

Full Report Registration: SNH4369C Printed: 07/11/2022 3:13 PM

Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

China Taiping Insurance (Singapore) Pte Ltd

Printed by:

Claim Reference:

Catherine Chong Kai Ling Currency: SNH4369C

TOYOTA

70 R4 01

SNH4369C

BASE MODEL

A201A0003468

RAV 4

SGD 01/11/22 Date of Incident: Hire Car Start:

Estimated Repair Time:

Actual Repair Days:

Hire Car End:

Vehicle Details

Vehicle

Manufacturer:

Model: Sub Model:

Registration: VIN number:

Model Sheet Number:

Odometer: **Model Specs**

TWO COAT METALLIC

PREPARE OFF VEHICLE

Audatex System Using Manufacturer Times

Page 1 of 4

PRINT DATE 07/11/2022




Vehicle Condition

Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

All Underbody



Tyres Condition

Tyre Brand Tread (Left Middle), Tread (Left Outer), Tread (Left Inner), Tread (Right Inner), Tread (Right Outer), Tread (Right

Condition

mm

mm

Middle), mm

Spare Tyre Brand

Tread (Spare), mm

Labour

Labour	Time Base 10 WU/h	Price = 42.	.00 SGD/h
Code	Description	WU	Price SGD
B020	RENEW FRONT BUMPER	16.0	67.20
	INCLUDES: R + R FRONT BUMPER, RADIATOR		
	GRILLE AND NECESSARY ATTACHED PARTS		
B125	R + R FRONT BUMPER REINFORCEMENT	3.0	12.60
B040	R + R LEFT HEADLAMP	4.0	16.80
	(BUMPER REMOVED)		
	INCLUDES: ADJUST HEADLAMPS.		
B040)	R + R R/HEADLAMP (ADD/WORK)	1.0	4.20
B100	REMOVE AND REFIT L/F MUDFLAP REAR	1.0	4.20
B100	REMOVE AND REFIT R/F MUDFLAP REAR	1.0	4.20
B110	RENEW L/FRT WING	8.0	33.60
	INCLUDES: WHEELHOUSE LINER AND REQUIRED		
	ATTACHED PARTS R + R		
	NOT INCLUDED: HEADLAMP AND		
	R + R BUMPER		
B110	RENEW R/FRT WING	8.0	33.60
	INCLUDES: WHEELHOUSE LINER AND REQUIRED		
	ATTACHED PARTS R + R		

Audatex System Using Manufacturer Times

Page 2 of 4

PRINT DATE 07/11/2022



de	Description				wu	Price SGD
y						
	NOT INCLUDED: HEADLAMP	AND				
	R + R BUMPER				5.0	21.00
B070	RENEW BONNET					
	INCLUDES: R + R BONNET, ATTACH PARTS ASSEMBLE AN	D IF NEC RENEV	N			504.00
N.N.	BONNET INSULATION R&R /	NEW PARTS		100/	120.0* 5.0*	
NN 0475	L/F HINGE REPAIR				5.0*	
0476	R/F HINGE REPAIR				5.0 /	
01110				Hrs	WU	
	Labour Cost	_		17.70	177.0	743.40
	Panel / Mechanical Labour	ps.				743.40
	Total of Labour					
Paint		SYSTEM AZT		Tir	ne Basis	10 WU/h
Paint Work					wu	Price SGD
Code	Description - TWO COAT M	ETALLIC				
	THE PART DATE THE				23.0	
	BONNET NEW PART PAINTING L/F WING NEW PART PAINTIN	ie I			10.0	
	R/F WING NEW PART PAINTIN	NG			10.0	
	FRONT BUMPER NEW PART PA	AINT KIR			10.0	
	THOM:					
Paint Materia	l Per Part					Price SGD
Code	Description				901	FIICE DOD
	THE PART PARTITION					73.27
0471	BONNET NEW PART PAINTING L/F WING NEW PART PAINTIN	ie I				20.64
0741	R/F WING NEW PART PAINTIN	NG				20.64 44.28
0742 0281	FRONT BUMPER NEW PART PA	AINT K1R				44.28
0201	THOM: DOTH					
				Hrs	wu	Price SGD
	Labour Cost - Paint		42.00 SGD/h			
	Factor				53.0	
	Time Paint Preparation Main Work Metal			2.50		105.00 21.00
	Preparation Comp. Work Plast	ic		0.50	5.0 83.0	348.60
	Total		10 WU/h	8.30	83.0	348.00
						Price SGD
	Material Cost - Paint					114.55
	New Part Painting	_				44.28
	New Part Painting - Plastic K1	R				28.60
	Material-constant Metal Prepa	ration				9.00
	Material-constant Plastic					196.43
	Total					
Canas Darts						06-01/01
Spare Parts				prices as	at 201:	5-06-01/01 Price SGD
Code	Description P	art Number	Part Source			71100 000
		2110 44004	Original			495.00
0281	FRONT BUMPER / 00) 5	2119 4A904	Oligina.			
		Page 3	of 4	PRIN	T DATE	07/11/2022
Audatex Syster	n Using Manufacturer Times	rage 3				

7.		Part Number	Part Source	Price SGI
de	Description	53128 42020	Original / M	90.00
J351	L/LOWER AIR GRILLE	53127 42040	Original / CuT	90.00
0352	R/LOWER AIR GRILLE		Original / CUT	220.00
0375	LOWER BUMPER COVER	53106 42010	Original 1	240.00
0415	L/GRILLE TRIM	53105 42010	Original ?	240.00
0416	R/GRILLE TRIM	52618 42050	Original 1	198.00
0417	BUMPER IMPACT	52010 42030		
	DAMPER	50000 40100	Original / B1	220.00
0419	FRT CTR BUMPER REINF	52029 42100	Original / OR	220.00
0421	LWR RADIATOR GRILLE	53112 42090	Original / M	33.00
0431	BADGE TOYOTA	75301 12400	Original / 00	440.00
0471	BONNET	53301 0R070	Original X	0.00
0481	BONNET INSULATION	53341 42090	Original / RR	880.00
0561	LEFT HEADLAMP ASSY	81170 42552	Original / (W	880.0
0562	RIGHT HEADLAMP ASSY	81130 42552	Original / 00	270.0
0741	L/F WING	53812 OR100	Original / M	270.0
742	R/F WING	53811 OR120		120.0
1000	UPPER	FRONT PANEL	Original / 87	
.000				0.0
: OEM Parts	Savings			4,906.00
n: Non-OEM Parts	Subtotal			
u: Used parts	-			4,906.00
	Total			
Final Calculat	ion		SGD	sgi
			4,906.00	4,906.00
Parts				4,500.0
Total Parts				
	ase 10 WU/h		743.40	
	/U X 42.00 SGD/h		743.40	743.40
	10 X 42.00 3GD/11			, , , , ,
Total of Labour				
	Dasa 10 WII/h		240.60	
Paint Work Tin	ne Base 10 WU/h		348.60 196.43	
Labour Cost 83	0.0 WU X 42.00 SGD/h		196.43	545.03
Material Cost	u - Material			545.0
Total Paint Incl	iding Material			6,194.4
	Lan CCT			433.6
Repair Cost Exc	ludes GS1			6,628.0
GST (+7.0%) Repair Cost Incl	uded GST (fove	(LKK)		0,020.0
tepan coor	- Luli	12, 1.00/-		
	8 1 11/3	11/1	LKK Auto Consultants hence	notify
	, ,	on . 1 1	the Repairer of the following	
		(11)- 12/ 11	• To resurvey before/after spray pa	
Comments		OD-MA	To resumely between and open of the state of the sta	3.10-20-11-7
CLIDDLIE	D DATA	EXCENT -	• Funcial of a land to confin	
NO MANUEA	CTURERS CODE EXISTS	0111		Trielogies were
WILL DADTIAL T	NCL IN OTHER POSITIONS	1/1	No auga monto status, in a vi-	bas bound and
- WO PARITAL		01	Supplementary (territs) must be r is subject to final approval from I	nsurance Company
	Note	11/1	is subject to final approval from t	
Assessment I			Acknowledged by Repairer	
No assessment	notes entered.	7].		
NO assessment		10	Signature:	
		J	Date:	
			DRINT DAT	TE 07/11/2022
	Manufacturer Times	Page 4	of 4	

Audatex System Using Manufacturer Times

SA1N22B10004 / Auto Insure Pte Ltd [608586] ENTRY DATE & TIME: 01/11/2022 17:42 (SGT) SUBMITTED BY: LIM WEI LING VERSION: 1 (01/11/2022 17:42 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

3. Information provided must be as truthful and accurate as possible. Any select this test and the insurance companies.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission

Reported by

Date of Accident

Exact Location of Accident

Additional Location Information

Country/State of Loss

01/11/2022 17:42 (SGT)

Both

01/11/2022 09:40 (SGT)

Bukit Panjang Rd, Singapore

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SNH4369C

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

NRIC No

Email Address Mobile Phone No

Alternative Phone No

VEHICLE PARTICULARS

No

LIM SWEE PANG

S7070575C

hrzone2003@yahoo.com.sg

(Phone) +65-97302406

Manufacturer Model

Variant

Toyota RAIZE 1.2X

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle?

Vehicle Category

Transmission

Yes Private car

Auto

1198

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

China Taiping Insurance (Singapore) Pte. Ltd.

MPC202200454CN

DRIVER

Name of Driver

NRIC No

Date Of Birth

Occupation

Accident report SA1N22B10004

LIM SWEE PANG

S7070575C

21/01/1970

Indoor

Page 1 of 28



Date Of Driving Pass Driving experience

Gender

Mobile Number Alt. Phone Number

Email Address Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

....

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident

Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged? Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

Translator's name Translator's ID

Translator's phone number

Translator's email

Original language used in the statement

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Was notice of intended Prosecution given?

If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

ON 1/11/2022, AT ABOUT 0940. I WAS DRIVING ALONG BUKIT PANJANG ROAD. VEHICLE B SUDDENLY BRAKE. I COULD NOT STOP ON TIME AND HIT ONTO VEHICLE B BACK PORTION.

14/04/1998

Male

310264

Yes

No

Clear

Dry

No

No

Yes

1

No

No

No

24 YEARS AND 7 MONTHS

hrzone2003@yahoo.com.sg

APT BLK 264 TOA PAYOH EAST #07-30

(Phone) +65-97302406

Collision - Head to Rear

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Manufacturer Vehicle Model

Vehicle Variant Vehicle Colour

Vehicle Category Name of Driver SLW3406E

SLV

:

Private car HAIVILAH

Accident report SA1N22B10004

Page 2 of 28





Page 3 of 28



SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- By the ladgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared (disclosed
 - (i) to all insurers and/or any other third parties that asset in evaluating lovestigating controlling or managing fraud, regulators, law enforcement and government agencies as resumably required for the purposes stated, or

(ii) for complying with requirements under any regulations, lows or court orders

Policyholder Sig Date & Time

Driver's Signature (if driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature

A.

NRIC/FIN No.





中国太平保险 (新加坡) 有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

\$1,563.06 ORIGINAL

MOTOR COVER NOTE

COVER NOTE NO.: MPC202200454CN AGENT CODE: ANG695A

- The Motor Vehicle (Third Party Bisks and Compensation) Act (Cap 169) Republic of Singapore; or
- The Agreement between the Minister of Finance (Singapore) and the Motor Insurers Bureau of Singapore dated 22 February 1975, or The Road Transport Act 1987 of Malaysia; or
- The Agreement between the Minister for Transport (Malaysia) and the Motor Insurer's Sureau of West Malaysia dated 30 March 1992:
- And any subsequent revisions to the above Acts and Agreements.

The insured mentioned in the Schedule, having proposed for insurance in respect of the Motor Vehicle described in the Schedule is hereby HELD COVERED under the terms of the Company usual form of Motor Policy applicable thereto for the period mentioned in the Schedule unless the cover be terminated by the Company by notice in writing in which cases the insurance will thereupon cease and a proportionate part of the annual premium writing in which cases the insurance will be charged for the time the Company has been on risk.

SCHEDULE

	LIM SWEE PANG
INSURED	TOYOTA RAIZE 1.2X
MAKE/MODEL OF VEHICLE	182.440
YEAR OF MANUFACTURE	2022
YEAR OF REGISTRATION	2022
ENGINE NO.	WA00038625
CHASSIS NO.	A201A0003466
ENGINE CAPACITY/TONNAGE	1198
TYPE OF COVER	Comprehensive
SUM INSURED	MARKET VALUE 20110100000000000000000000000000000000
PERIOD OF INSURANCE	
	Named Drivers Ex Sect. 1 : S\$500.00
XCESS	VES
AUTHORISED WORKSHOPS	CREDIT PTE LTD
HIRE PURCHASE CO.	TECK WEI CREDIT

I/We hereby certify that the Folicy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Farty Risks and Compensation) Act (Chapter 189) and part IV of the Road Transport Act, 1987 (Malaysia)

Not valid unless counter signed by Authorised Agent CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

TECK WETCREDIT LITEX! TECH WEI CREDIT PTE LTD

Authorised Signature

Agent Name & Date

PREMIUM PAYMENT WARRANTY

For Individual Customer: Please mote that the premium in full should be paid before inception date shown above in order for the insurance cover to be valid

For non-individual customer.

Please note that where the period of cover is for more than 60days, the premium in full should be paid within 60days on inception/renewal/endorsement. For all other cases, the premium in full should be paid before

IMPORTANT NOTICE: THIS COVER NOTE IS VALID FOR 30DAYS FROM 26-10-2022

China Taiping Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200206384E) A 3 Anson Road #16-00 Springleal Tower Singapore 079909

Q63896111

@6222 1033

www.sg.cntaiping.com

Accident report SA1N22B10004

Page 5 of 28

