

 Service Request Details

Claim	S2M04E80
Reference	CS3/ASM22011209/Tnp3m4 
Loss Date	3 November 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	8 Nov 2022 11:11:49 AM
Request Date	8 November 2022
Due Date	

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident	SMM2885C
Vehicle	
Registration #	
Make	tpvd- Honda
Model	Fit

Service Address

, , ,

Primary Contact/Insured

Services

Pre-Repair Survey

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

TEO Kitty

kitty.teo@axa.com.sg

Additional Instructions

- Messages2
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 TP PRI PDF.pdf	Other	Other	do not reply	
 ASM-LKKInvoice-AC2207796.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD	20 December 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
			(TP)	
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2022
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2022
 AXA Immediate Advice - SMM2885C (PRS).pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 December 2022
 TP PRI.msg.msg	Letters and Correspondence	Workshop	PODUVAL Akash	8 November 2022
 SH7480J OI GIA.pdf.pdf	Reports & Statement	GIA Report	PODUVAL Akash	8 November 2022
 SMM2885C TP GIA.pdf.pdf	Reports & Statement	GIA Report	PODUVAL Akash	8 November 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 TP PRI PDF.pdf.pdf	Letters and Correspondence	Workshop	PODUVAL Akash	8 November 2022
 REJECTION ACK.msg.msg	Letters and Correspondence	Others	PODUVAL Akash	8 November 2022