

AGS REC BY: Toupin

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: 5HA 9188 M Yr Regn: 2017 1 Sep.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.O. 1798

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STDK63F4 003564230

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 03/10/22

Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. invs (\$ _____)

☐ : Weekend (\$ _____)

S + RS. \$ _____

Photos _____

Others _____

Rep. Form: _____

Lum. Sum / I. Bal. / P. _____

REPAIR ESTIMATE

VEHICLE NO SHA9188H

MAKE : TOYOTA

MODEL : PRIUS

DOA 30.09.22

INS. INCOME

MVA JUMANI

CL/Sum

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
FRT BUMPER	1		\$ 586.18
FRT BUMPER CLIPS	10		\$ 22.00
FRT FENDER RH	1		\$ 1,111.93
FRT BUMPER SIDE RETIANER RH	1		\$ 90.75
FRT BUMPER FOG LAMP RH	1		\$ 920.00
FRT FENDER EMBLEM RH	1		\$ 86.50
HEADLAMP ASSY RH	1		\$ 2,735.28
SUB TOTAL			\$ 5,552.64
LESS 25%			\$ 1,388.16
DISCOUNTED TOTAL			\$ 4,164.48
FRT ADVERTISEMENT LOFO - FENDER			\$ 100.00
NET			\$ 100.00
LABOUR CHARGE			
PANEL BEAT			\$ 350 800.00
SPRAYPAINT			\$ 500 600.00
CHECK WIRING			\$ 30 50.00
TUFF KOTE			\$ 30 50.00
TOTAL LABOUR			\$ 1,500.00
ESTIMATE TOTAL			\$ 5,764.48

Tanjum 97495749
 WP 3/10/22 5pm
 1/2 Rising after repair
 tanjumi@khambo.com
 2 days

LRK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 01.10.2022 09:06

Page : 1

m: ARC Repair TP(CFSO)1

JOB CARD Sales Order:

JC NO 805531870

OWNER

IS CITYCAB PTE LTD

OWNER NO 7010070

ADDRESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65551188

(O)

(P)

OUNT CARD NO.

REGN NO:

SHA9188H

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)30.09.2022 15:55

DATE/TIME IN

YR OF MANU.

28.09.2017

TARGET DATE

CHASSIS CODE

JTDKB3FU003564230

COMPLETION DATE/TIME:

JOB DESCRIPTION


cident Date: 30.09.2022

TURE: 3P.30.09.22

NO

LABOR CODE

DESCRIPTION



BOOKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

acknowledgement Slip

Exit Pass

Vehicle No.: SHA9188H

JU INCOME

Vehicle No.:

SHA9188H

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard