

ASS. REC. BY: Tou Jm

REF:

INC.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Ms Loke Vehicle: IN / OUT

Veh No: SHC8462L Yr Regn: 2021 Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Lorry C.D. 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 251676 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHC851CVL4792838

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NH / S/Rim / STD A/Rim or

Tyre Size: F: 145/65R15

R: 22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Wu Hoke

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

D.O.I. 3/10/22

Survey held at

Comfort Lorry

Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

Survey Fee: _____

Transportation: _____

Report Format: _____

Lum Sum / LB or TP

☐ : Interview (\$ _____)

Photos _____

☐ : Tech. Invs (\$ _____)

Others _____

☐ : Weekend (\$ _____)

REPAIR ESTIMATE

Model : IONIQ(G3)

Insurance: INCOME

MVA: MS. LOKE YY

Tanji 97495749
wp 3/10/22 e 345
2 days
p rising new ports
anjia clh auto com

Date:

Date/Time: 03.10.2022 10:55

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4944600

JC NO 805531967

TOMER

MS COMFORT TRANSPORTATION PTE LTD

TOMER NO. 7010045

RESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

OUNT CARD NO.

REGN NO.:

SHC8462L

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

03.10.2022 10:15

DATE/TIME IN

YR OF MANU.

28.01.2021

TARGET DATE

CHASSIS CODE

KMHC851CVLU192838

COMPLETION DATE/TIME:


JOB DESCRIPTION

cident Date: 30.09.2022
PURE: 3P 30.09.2022

VO

LABOR CODE

DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

Vehicle No.:

SHC8462L

SHC8462L

YY

Service Advisor

Signature/Date

Name of Service Advisor

Date

ed to Service Reception upon collection

To be kept by Security Guard