

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC22011226/Tqcq2		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	15-11-2022 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	YN 840Y	Veh. In	spected	SHC 8747R	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1191246-002	Excess	s (\$)	0.00	
	Assign From		Assign	n Date	03/10/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI 140	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2016	
	Chassis No.	KMHLB41UMGU083225	Colour	r	BLUE	
	Odometer	685104	Steerin	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	WEST L	LAKE	6 mm	
	L/H Front Tyre	205/60 R16	WEST I	LAKE	6 mm	
	R/H Rear Tyre	205/60 R16	WEST I	LAKE	6 mm	
	L/H Rear Tyre	205/60 R16	WEST I	LAKE	6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	03/10/2022	Inspection Date 03/10/2022			
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	a. Remarks					
	N)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  1)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					