

Our Job Ref No : 305531872  
Date : 10/10/22

**COMFORTDELGRO**  
**ENGINEERING**

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK Fax :  
Attn : Mr Taufikh  
Vehicle Reg No. : SHD7222P 30.09.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **INCOME** -- **FBM 92S**
2. The finalized amount shall be:
- (a) Spare Parts after List discount
- (b) Labour Charges
- Total for Part-By-Part Repair Cost** **\$0.00**
- (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20% **\$3,450.00**  
**Final Lumpsum Repair cost** **\$3,450.00**

3. Estimated normal period for repairs: 3 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and  
finalized amount

Signature :  
Name : Ms. Loke YY  
Tel : 62148355  
Fax : 65468156

Signature : *taufikh*  
Name : Taufikh  
Date : 10/11/22

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

# COMFORT DELGRO ENGINEERING

VEHICLE I SHD7222P

TYPE OF C: TP

INCOME

SURVEY B: LKK/ TAUFIKH

305531872

DATE : 10/10/2022

## SUPPLEMENTARY OF PARTS AND LABOUR COSTS

DESCRIPTION	QTY	ESTIMATE	\$	REMARKS
ARM ASSY-RR TRAILING ARM RH	1		\$265.40	bt ✓
WHEEL ASSY-ALUMINIUM (BLACK)	1		\$1,124.20	bt ✓
		TOTAL	\$1,389.60	✓