

AS: S. REC: BY: T. J. M.

REF:

CS3/CT. 22011278/Tny 3

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_


Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

\$52K

IDAC Accident Report \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

20

days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP' PRS

Vehicle: IN / OUT

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Veh No: GBF672E

Yr Regn: 2016

June

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna

C.C. 2982

Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 118270

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTFAT 35470K 206360

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195/15C

R: 185/12C

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6/6 mm

L/Bal. 6 mm

L/Bal. 6/6 mm

D.O.A. \_\_\_\_\_

D.O.I. 10/11/22 @ 45pm

Survey held at Transport Battery

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frnt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair range: \$20000 - \$22000, 20 days.

22/11/22 submit PRS

repair range: \$20k-\$22k and 20 days

Date/Time, File Pass to?

☐

: Prel. Report

1) 22/11/22

☐

: Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Repair Form: PRS

Lum Sum: \$20k-\$22k

Days Of Repair: 20

Resurvey No. of Trip: 1

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. SI

Photos

Others

Add Fee: \_\_\_\_\_

☐

: Site Insp (\$ \_\_\_\_\_)

☐

: Interview (\$ \_\_\_\_\_)

☐

: Tech. ins (\$ \_\_\_\_\_)

☐

: Weekend (\$ \_\_\_\_\_)