

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile									
	EQ INSURANCE C	OMPANY LTD		Ref:	CS/EQI22011288/Uqy3				
	5 MAXWELL ROAL #17-00 TOWER BL MND COMPLEXSI	OCK		Date:	10/11/2022				
				Code:	EQI				
1.		Policy Particulars :	- THIRD PARTY CLAIM						
	Insured Veh.	GBH 704L	Veh. Inspected	i	SMY 405E				
	Policy No.		Coverage (\$)		0.00				
	Claim No.		Excess (\$)		0.00				
	Assign From	JOSEPHINE WONG	Assign Date		10/11/2022				
2. Vehicle Particulars & Condition									
	Make & Model		c.c		0				
	Engine No.	HIDDEN	Year of Reg.						
	Chassis No.		Colour						
	Odometer	Steering							
	Brakes		Modification						
	General								
3. Conditions of Tyres									
		Size	Make		Balance				
	R/H Front Tyre				mm				
	L/H Front Tyre				mm				
	R/H Rear Tyre				mm				
	L/H Rear Tyre				mm				
4.		Description	on of Damages						
5.	5. General Information								
	Accident Date	08/11/2022	Inspection Dat	e	10/11/2022				
	Survey held at	AUTOLUTION INDUSTRIAL PTE LTD							
		19 UBI ROAD 4 SINGAPORE 408623							
5a.		Re	emarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.								

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD #17-00 TOWER BLOCK

MND COMPLEXSINGAPORE 069110

Ref: CS/EQI22011288/Uqy3

Date: 10/11/2022

Code: EQI

	Affiliated to Federation Internationale Des Experts En Automobile							
1.	Policy Particulars :- THIRD PARTY CLAIM							
	Insured Veh.	GBH 704L	Veh. Inspected	SMY 405E				
	Policy No.		Coverage (\$)	0.00				
	Claim No.		Excess (\$)	0.00				
	Assign From	JOSEPHINE WONG	Assign Date	10/11/2022				
2. Vehicle Particulars & Condition								
	Make & Model		c.c	0				
	Engine No.	HIDDEN	Year of Reg.					
	Chassis No.		Colour					
	Odometer	-	Steering					
	Brakes		Modification					
	General							
3.		Conditi	ons of Tyres					
		Size	Make	Balance				
	R/H Front Tyre			mm				
	L/H Front Tyre			mm				
	R/H Rear Tyre			mm				
	L/H Rear Tyre			mm				
4.		Description	on of Damages					
5.		Genera	Information					
	Accident Date	08/11/2022	Inspection Date	10/11/2022				
	Survey held at	AUTOLUTION INDUSTRIAL PTE LTD						
		19 UBI ROAD 4 SINGAPORE 408623						
5a.	Remarks							
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							