(08/11/13) wef

ASS. REC. BY: Marcus

REF: CS/FC/22011302/Uvy3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SZJ 6128G

at Workshop m/s Quen De

of

Insured: SBS3449X

Policy No.

Claims No. D22003478MFBP

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: $ 60k.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS C 16/e

Vehicle: IN / OUT

Date: Person Contacted: L7A832277

Veh No: SZJ 6128G Yr Regn: 19/12/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or SA/

Make: Toyota corolla Altis c.c 1598

Colour white A/C: Insured / Std / NI / NA

Sp.Reading 163594 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR053REH104548889

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55-R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Keepser

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	03/11/22	D.O.I.	11/11/22

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Dep 13k
	No second hand parts
27/12/22	L/S $ 1200 informed Jennifer

(red 1544.25, 56%)

Date/Time, File Pass to? 1) ☐ : Preli. Report ☐ : Final Report

Date/Time, File Return to? 2) 27/12/22-typist

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($) __S + RS.__SI ☐ : Interview ($) Photos ☐ : Tech. Invs ($) Others ☐ : Weekend ($)

Report Format : TP

Lump Sum / ~~I.B.I~~: ($ 1200)

Survey Fee:	110
Transportation:	50
	50
	31
TOTAL	241