ASS, REG. BY: ASS	IGNMENT
From: Date:	Veh No: SJB323P Yr Regn: 2021 April
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Andi AS SB. c.c 1884
at Workshop m/s	Colour Black A/C: Insured / Std / NI / NA
1.	22.11
insured:	-
	Eng/No: WAUZZZFSSMA039+717
Policy No.	Gen. Cond: Good / Fair / Poor / Burnt
Claims No	Steering: Inorder / Jammed / Leaked / Burnt or
	Brake: Inorder / Jammed / Leaked / Burnt or
(Client's Record)  Make of Veh:	Modi: Nil /\$/Rim / STD A/Rim or
	Tyre Size: F: 2 45/40818
(Policy Condition)	R: 245/40818
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Hankook.
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. of mm R/Bal. of mr
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 06 mm L/Bal. 06 mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 15/1/22
Lum Sum: % 3 Val.: Yes or No	Survey held at Premium
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	Reer 6/5.
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time   Action / Instruction   TP China	•
· CVVIIIA	
mv:	
PV:	
Nett:	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
; Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
Date/Time, File Return to?  Add Fe	(===)

Report to the France Fig. 10 for 10 for

SP1822B90001 / PROGRESSIVE CAR CARE PTE LTD ENTRY DATE & TIME: 09/11/2022 09:41 (SGT) SUBMITTED BY: Liang Siew Chin VERSION: 1 (09/11/2022 09:41 (SGT))

Accident report SP1822B90001



## SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

(1) Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDEN	IT STATEMENT
Date of Submission	09/11/2022 09:41 (SGT)
Reported by	Both
Date of Accident	08/11/2022 16:00 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	PIE, SINGAPORE PIE TOWARDS UBI NEAR KALLAG EXIT SINGAPORE
Country/State of Loss	Singapore
Soundly/State of Loss	Singapore
DETAILS O	OF OWN VEHICLE
Vehicle Registration Number	SJB323P
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	NG THIAM SIONG
NRIC No	S7042422C
Email Address	BENEDICT.TS.NG@GMAIL.COM
Mobile Phone No	(Phone) +65-82228212
Alternative Phone No	-
VEHICLE PARTICULARS	
Manufacturer	Audi
Model	A5
Variant	AUDI / A5 SPORTBACK 2.0 TFSI S TRONIC (110 KW)
Exact purpose for which vehicle was being used at time of	And the state of t
accident	Private use
Are you claiming under your own insurance policy for repair to	
your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
cc	1984
INSURANCE COMPANY	
Name of Insurance Company	FWD Singapore Pte. Ltd.
Policy Number / Cover Note Number	PNPV2021-00002069-01
Control Provide Control of the Contr	
DRIVER	
Name of Driver	NG THIAM SIONG
NRIC No	S7042422C
Date Of Birth	23/11/1970
Occupation	Indoor

Date Of Driving Pass 01/08/1989 Driving experience 33 YEARS AND 3 MONTHS Gender Male Mobile Number (Phone) +65-82228212 Alt. Phone Number **Email Address** BENEDICT.TS.NG@GMAIL.COM Address 28 TOMLINSON ROAD #13-30 Address complement Postcode 247854 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Raining Road Surface Wet OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement PASSENGER 1 Name PAX 1 Gender Female **DETAILS OF POLICE ACTION** Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO ATTACHED STATEMENT RECORDED BY ANNIE - PROGRESSIVE CAR CARE PTE LTD TEL 67415336 ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes **DETAILS OF OTHER VEHICLE PROPERTY 1** 

SND1507L

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model	-
Vehicle Variant	
Vehicle Colour	•
Vehicle Category	Private car
Name of Driver	-
NRIC No	S9476262F
Contact Number	(Phone) +65-97700506
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as <u>truthful</u> and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")


- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes\_\_\_\_\_

Policyholder's Signature Foate & Time

Oriver's Signature (if driver is not the policyholder) / Date 8. Time

Witnessed by Beporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan



1

It was raining	around 3.55 pm, I was driving along words usi Road, owner of Lexus Cor barged into my car rear right.
by bit heavy incident year because the car stop. From that the vehical stoppold	and slow moving. At the time of the Kellang exit, I slowed down and stop in that of the has applied brake and he dash can footage, it can be seen the BND1507L did not stop in time of the right shoulder of the expression my car as well.
you nother of heavened they	my car to check the damage and  The driver of mit is their mistake  dil not mayor manage to stop in time  to claim against the owner Idrives el the photos and dish can tootage

#### Declaration

I/We declare the foregoing particulars are true in every respect.

If you wish to claim against your own policy, please be advised that your insurer may have a fourteen (14) days clause whereby the claim must be made within the stipulated time trame from the day of occurence. Kindly check with your insurer for more details.

Policyhoide(s Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

# \* PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** 

: ACCIDENT REPAIRS

WORKSHOP

UBI ROAD 1

**CONTACT NO** 

6366 2323

**FAX NO** 

6841 1183

REFERENCE

: PA/TP/0992/2022/EQ

DATE

11-Nov-22

WIP

: 49841

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 15/11/2022

YOUR INSURED VEH NO: SND 1507 L

China Taiping Insurance (S) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Attn: Motor Claims Dept

**OWNER'S NAME** 

: MR NG THIAM SIONG

**ADDRESS** 

28 TOMLINSON ROAD

#13-30

SINGAPORE 247854

TELEPHONE

: HP +65 82228212

TYPE OF CLAIM

: THIRD PARTY CLAIM

**POLICY NO** 

PNPV2021-00002069-01

**VEHICLE NO** 

: SJB 323 P

MODEL CODE

: AUDI A5 SPORTBACK 2.0 TFS

MODEL YEAR

: 30/4/2021

**ENGINE NO** 

DEM 031679

CHASSIS NO

: WAUZZZF55MA039717

MILEAGE

\_

DATE IN

**ESTIMATED BY** 

: JOHNNY BOO / ALLAN WU

ACCIDENT DATE

8-Nov-22

PLACE OF ACCIDENT

: PIE TOWARDS UBI NEAR KALLANG

**EXIT SINGAPORE** 





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJB 323 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N	\$ 360.00	A V
2	TO RENEW 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER.	S/N	\$ 300.00	
3	TO INSTALL SOLAR FILM FOR AFFECTED GLASSES.	S/N	\$ 400.00	/
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N	\$ 1,600.00	
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N	\$ 1,600.00	
6	TO DISMANTLE AND RENEW REAR BUMPER. TO REMOVE AND REINSTALL RHS SILL PANEL TRIM. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 6,400.00	4800.
	TOTAL LABOUR CHARGES	;	\$ 10,660.00	-







EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

#### ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJB 323 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS SILL PANEL, ROOF CHANNEL, DOOR ENTRANCE, DRAIN CHANNEL AND REAR END PANELLING.		\$ 5,500.00	3600,
8	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N	\$ 280.00	X
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	/
	TOTAL LABOUR CHARGES	:	\$ 16,632.00	-





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJB 323 P

#### **DAMAGED PARTS & PRICES**

5/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER Deld	1	\$ 2,609.00	
2	REAR BUMPER SECURING STRIP	1	\$ 125.00	
3	REAR BUMPER SECURING STRIP	1	\$ 249.00	
4	REAR BUMPER SPOILER	1	\$ 276.00 ×	
5	REAR BUMPER REFLECTOR - LH / RH M M	2	\$ 96.00 🗡	
6	REAR OUTER TAIL LIGHT - RH WITCH	1	\$ 1,269.00	
7	REAR BUMPER GUIDE SECTION - RH UPPER	1	\$ 26.00	
8	REAR BUMPER GUIDE SECTION - RH	1	\$ 49.00	
9	REAR PARKING AID SENSOR - INNER / OUTER ** ** ** ** **	2	\$ 531.00 <del>+</del>	
10	REAR PARKING AID SEAL RING MY W	4	\$ 10.00 +	
11	REAR SIDE PANEL - RH Develd	1	\$ 4,076.00	
12	REAR QUARTER WINDOW - RH	1	\$ 798.00	
13	REAR FUEL INSERT Newwer	1	\$ 100.00	
14	REAR WHEEL HOUSING LINER - RH We per	1	\$ 299.00	
15	ATTACHMENT PARTS Noe wee	1	\$ 136.00 🗶	
16	ADHESIVE TAPES	1	\$ 221.00	
17	REAR VENT TRIM the new	1	\$ 75.00 +	
18	REAR ALUMINIUM RIM the we	1	\$ 1,889.00 4.	
19	REAR ALUMINIUM RIM VALVE	1	\$ 4.00 *	
20	REAR PARKING AID SENSOR	1	\$ 266.00	
	SUB TOTAL SPARE PARTS	:	\$ 13,104.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJB 323 P

## **DAMAGED PARTS & PRICES**

S/N	PARTS DESCRIPTION	QTY	 S/NETT	REMARKS
21	1/4 GLASS SEALANT	S/N	\$ 100.00	
22	ACRYLIC SEALANT	S/N	\$ 180.00	
23	CAVITY WAX Nec	S/N	\$ 140.00	
24	STONE CHIP	S/N	\$ 180.00	
25	METAL FILLER POWDER	S/N	\$ 280.00	
26	SUNDRIES ?		\$ 500.00	
	TOTAL SPARE PARTS	:	\$ 14,484.00	
	TOTAL LABOUR CHARGES	:	\$ 16,632.00	
	GRAND TOTAL	:	\$ 31,116.00	

mark :

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

# **PREMIUM** AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

Adrian Ling.

AUTHORISED DATE **EXCESS COST** 

LIABILITY

REMARKS

:

not Anthorsed, 13 Days.

**PLEASE NOTE** 

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY, PREMIUM AUTOMOBILES PTE LTD

> LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

were . . . F

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO BODY REPAIR MANAGER **ALLAN WU CLAIMS CONSULTANT**