	O11326/Acp3 SSIGNMENT
From: Date:	Veh No: SJB323P Yr Regn: 2021 April
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	1 1 7 - 00
at Workshop m/s	c.c /) 8 9
of	2001
nsured:	Sp.Reading 22/40 T/Radio: Insured / Std / NI / NA Eng/No:
Policy No.	C/No: WAUZZZF55MA039+717
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil /S/Rim / STD A/Rim or
	Tyre Size: F: 2 4 5 / 40 R 18
(Policy Condition)	R: 245/40818
emark: The veh had commenced its N/S O/S	
repair at the time of inspection.	TOYO/YOKO OF tar kook.
al. or Market Value:	Front Rear
OAC Accident Rport: Consistent? : Yes or No	R/Bal.
IA / PR Seen: Consistent?: Yes or No	L/Bal. 06 mm L/Bal. 06 mm
st. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 15/11/22
ım Sum: % 3 Val.: Yes or No	Survey held at
A / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OU ate: Person Contacted:	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
TP China	
	4 days with Carrine. (Red. 9789, 70, 31%)
	+ aug with campe. (red. 4+84, +0, 31%)
mv :	
PV:	
Nett:	
	·
/Time, File Pass to? : Preli. Report	Days Of Repair: 14
: Final Report	Resurvey No. of Trip: Survey Fee:
	- Carrey 1 56.
/Time, File Return to?	Transportation:
Time, File Return to?	Transportation: Size Insp. (\$) _ 8 + R8 _ 51

SP1822B90001 / PROGRESSIVE CAR CARE PTE LTD ENTRY DATE & TIME: 09/11/2022 09:41 (SGT) SUBMITTED BY: Liang Siew Chin VERSION: 1 (09/11/2022 09:41 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT Date of Submission 09/11/2022 09:41 (SGT) Reported by Date of Accident 08/11/2022 16:00 (SGT) Exact Location of Accident PIE, Singapore Additional Location Information PIE TOWARDS UBI NEAR KALLAG EXIT SINGAPORE Country/State of Loss Singapore **DETAILS OF OWN VEHICLE** Vehicle Registration Number SJB323P INSURED/POLICYHOLDER Is company? Name Of Registered Owner NG THIAM SIONG NRIC No S7042422C **Email Address** BENEDICT.TS.NG@GMAIL.COM Mobile Phone No (Phone) +65-82228212 Alternative Phone No VEHICLE PARTICULARS Manufacturer Audi Model A5 AUDI / A5 SPORTBACK 2.0 TFSI S TRONIC (110 KW) Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private car Transmission Auto CC 1984 INSURANCE COMPANY Name of Insurance Company FWD Singapore Pte. Ltd. Policy Number / Cover Note Number PNPV2021-00002069-01 DRIVER Name of Driver NG THIAM SIONG NRIC No S7042422C Date Of Birth 23/11/1970 Occupation Indoor

Date Of Driving Pass	01/08/1989
Driving experience	33 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	
Alt. Phone Number	(Phone) +65-82228212
Email Address	PENEDIOT TO NO COMMIL COM
	BENEDICT.TS.NG@GMAIL.COM
Address	28 TOMLINSON ROAD #13-30
Address complement	-
Postcode	247854
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	
	-
Insurance Company of Other Vehicle Owned by Driver	-
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident	0.1111111111111111111111111111111111111
	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet
OTHER INFORMATION	
Was any faraign vahiala involved in the assident?	· Ma
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	•
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s)	
soliciting/offering accident claims assistance?	No
Translator's name	_
Translator's ID	
Translator's phone number	
Translator's email	
Original language used in the statement	-
Original language used in the statement	•
PASSENGER 1	
Name	
Name	PAX 1
Gender	Female
DETAILS OF POLICE ACTION	
Was the accident reported to the police?	No
Was notice of intended Prosecution given?	
	No
If yes, against whom?	
CIRCUMSTANCES OF ACCIDENT	
DEEED TO ATTACHED	
REFER TO ATTACHED STATEMENT RECORDED BY ANNIE - PROGRESSIVE CAR CA	ARE PTE LTD
TEL 67415336	ANE FIE EID
122 07410000	
ATTACHMENT(S)	
Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
	. 55
DETAILS OF OTHER	R VEHICLE PROPERTY 1
Vehicle Registration Number	SND1507L
Vehicle Manufacturer	-

Vehicle Model	
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	
Name of Driver	Private car
	-
NRIC No	S9476262F
Contact Number	(Phone) +65-97700506
Address	-
Address complement	
Postcode	-
Insurance Company Name	-
Natura Of Damaga	-
Details of property damaged in accident	-
	-
No. Of Passenger (Including Driver)	_

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the todgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or no lices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes_____


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date

& Tim

Witnessed by Beporting Centre Personnel (Name as in NRIC/ID card)





Describe Circumstance of the Accident
On Oct 3th at around 3.55 pm, I was driving along PIE heading towards UBI Road, owner of Lexus Car (SND 1507 L) baged into my car rear right.
PIE heading towards up and owner of Lexit car
(SND 1507 L) barged into my car roar right.
It was a successful that the tradition
by bit heavy and slow moving. At the time of the
by bit heavy and slow moving. At the time of the incident good Kelleng exit, I slowed down and stop
December 11/2 (at in Firmat on the new ord harve - U
Stop. From the dash can footage, it can be seen that the vehicle 84015074 did not stop in time
that the vehicle 8ND1507L die not of all
and stoerol to the right shoulder of the expressival
and banging my car as well.
0) 0 2 2 2011.
There a was a passagger with me.
I got out of my car to check the dange and the mother of the driver of mit is their motake because they did not mayo manage to stop in time
the mother of the driver almit is their in take
because they did not more manage to the in the
maringe to stop to and
I would like to claim against the owner Idriuse and I attacked the photos and dish can tootage for evidence.
and I attacked the whotes and dally can testage
for ev. I wee.

Declaration

I/We declare the foregoing particulars are true in every respect.

If you wish to claim against your own policy, please be advised that your insurer may have a fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence. Kindly check with your insurer for more details.

Policyholde(s Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Winessed by Reporting Centre Personnel (Name as in NRICriD card)

2

am

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Xintu

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJB 323 P

DAM	MAGED	PARTS	&	PRICES

S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS	
1	REAR BUMPER Deld	1	\$	2,609.00		
2	REAR BUMPER SECURING STRIP 7.	1	\$	125.00 ?		
3	REAR BUMPER SECURING STRIP ?	1	\$	249.00 ?		
4	REAR BUMPER SPOILER AM M	1	\$	276.00 ×		
5	REAR BUMPER REFLECTOR - LH / RH N W	2	\$	95.00 K		
6	REAR OUTER TAIL LIGHT - RH WITCH	1	\$	1,269.00	- 000-	
(7)	REAR BUMPER GUIDE SECTION - RH UPPER	1	\$	26.00 2	XOS.	
(8)	REAR BUMPER GUIDE SECTION - RH	1	\$	49.00 2	86.5	
9	REAR PARKING AID SENSOR - INNER / OUTER XH / N	2	\$	531.00 +		
10	REAR PARKING AID SEAL RING ~~~	4	\$	10.00 +		
11	REAR SIDE PANEL - RH Devild	1	\$	4,076.00 L		
12	REAR QUARTER WINDOW - RH NCA	1	\$	798.00		
13	REAR FUEL INSERT Reviewer	1	\$	100.00 +		
14	REAR WHEEL HOUSING LINER - RH Le per	1	\$	299.00		
15	ATTACHMENT PARTS ALL NEL	1	\$	136.00 ≿		
16	ADHESIVE TAPES ?	1	\$	221.00 ?		
17	REAR VENT TRIM the new	1	\$	75.00 X		
18	REAR ALUMINIUM RIM & Note me	1	\$	1,889.00 4		
19	REAR ALUMINIUM RIM VALVE 1500 M	1	\$	4.00 ×		
20	REAR PARKING AID SENSOR At m	1	\$	266.00 A		
	SUB TOTAL SPARE PARTS	:	\$	13,104.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED SPARE PARTS ARE SPECIAL NETT.

Resurreged Mariaa Co



\$21326.30

TP - China Taiping

55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE

: ACCIDENT REPAIRS

WORKSHOP

UBI ROAD 1

CONTACT NO

: 6366 2323

FAX NO

6841 1183

REFERENCE

PA/TP/0992/2022/EQ

DATE

: 11-Nov-22

WIP

49841

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 15/11/2022

YOUR INSURED VEH NO: SND 1507 L

China Taiping Insurance (S) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

OWNER'S NAME

Attn: Motor Claims Dept

MR NG THIAM SIONG

ADDRESS : 28 TOMLINSON ROAD

#13-30

SINGAPORE 247854

TELEPHONE : HP +65 82228212

TYPE OF CLAIM : THIRD PARTY CLAIM

POLICY NO : PNPV2021-00002069-01

VEHICLE NO : SJB 323 P

MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS

MODEL YEAR : 30/4/2021 ENGINE NO : DEM 031679

CHASSIS NO : WAUZZZF55MA039717

MILEAGE :

DATE IN : -

ESTIMATED BY : JOHNNY BOO / ALLAN WU

ACCIDENT DATE : 8-Nov-22

PLACE OF ACCIDENT : PIE TOWARDS UBI NEAR KALLANG

EXIT SINGAPORE



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJB 323 P

S/N	NATURE OF JOBS		ı	STIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N	\$	360.00	& V
2	TO RENEW 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER.	S/N	\$	300.00	/
3	TO INSTALL SOLAR FILM FOR AFFECTED GLASSES.	S/N	\$	400.00	
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N	\$	1,600.00	
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N	\$	1,600.00	
6	TO DISMANTLE AND RENEW REAR BUMPER. TO REMOVE AND REINSTALL RHS SILL PANEL TRIM. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$	6,400.00	4800.
	TOTAL LABOUR CHARGES	;	\$	10,660.00	- -





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJB 323 P

			E	STIMATED	SURVEYOR'S
S/N	NATURE OF JOBS			CHARGES	RECOMMENDATIONS
7	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS SILL PANEL, ROOF CHANNEL, DOOR ENTRANCE, DRAIN CHANNEL AND REAR END PANELLING.		\$	5,500.00	3600,
8	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N	\$	280.00	X
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$	192.00	/
	TOTAL LABOUR CHARGES	:	\$	16,632.00	
					•





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJB 323 P

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER Deld	1	\$ 2,609.00	
2	REAR BUMPER SECURING STRIP	1	\$ 125.00	
3	REAR BUMPER SECURING STRIP AND MAN	1	\$ 249.00	
4	REAR BUMPER SPOILER	1	\$ 276.00 ×	
5	REAR BUMPER REFLECTOR - LH / RH	2	\$ 96.00 🗡	
6	REAR OUTER TAIL LIGHT - RH ANT h	1	\$ 1,269.00	
7	REAR BUMPER GUIDE SECTION - RH UPPER REAR BUMPER GUIDE SECTION - RH REAR BUMPER GUIDE SECTION - RH	1	\$ 26.00	25.20
8	REAR BUMPER GUIDE SECTION - RH	1	\$ 49.00	48.80
9	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 531.00 +	
10	REAR PARKING AID SEAL RING $$	4	\$ 10.00 +	
11	REAR SIDE PANEL - RH Devild	1	\$ 4,076.00	
12	REAR QUARTER WINDOW - RH	1	\$ 798.00 /	797.50
13	REAR FUEL INSERT Newwer	1	\$ 100.00 🗡	
14	REAR WHEEL HOUSING LINER - RH Le M	1	\$ 299.00	
15	ATTACHMENT PARTS NO ME	1	\$ 136.00 ×	
16	ADHESIVE TAPES Nel New	1	\$ 221.00	
17	REAR VENT TRIM the new	1	\$ 75.00 ¥	
18	REAR ALUMINIUM RIM LES NOC ME	1	\$ 1,889.00 4	
19	REAR ALUMINIUM RIM VALVE AND ME	1	\$ 4.00 ×	
20	REAR PARKING AID SENSOR	1	\$ 266.00 🖈	
	SUB TOTAL SPARE PARTS	:	\$ 13,104.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJB 323 P

DAMAGED PARTS & PRICES

S/N	PART:	DESCRIPTION	QTY	S/NETT	REMARKS
21	1/4 GLASS SEALANT	Ò	S/N	\$ 100.00	
22	ACRYLIC SEALANT		S/N	\$ 180.00	
23	CAVITY WAX	Nec	S/N	\$ 140.00	
24	STONE CHIP		S/N	\$ 180.00	
25	METAL FILLER POWDER		S/N	\$ 280.00	
26	SUNDRIES WW			\$ 500.00	37.80
	TOTAL SPARE PARTS	5	:	\$ 14,484.00	
	TOTAL LABOUR CHA	RGES	:	\$ 16,632.00	
	GRAND TOTAL		:	\$ 31,116.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Adrian Luy.
15/11/22 Plys

Not Anthorsed, 18 Days

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER

LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF

REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR

APPOINTMENT.

YOURS FAITHFULLY, PREMIUM AUTOMOBILES PTE LTD

> LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No il egal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TP. T

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO **BODY REPAIR MANAGER** ALLAN WU **CLAIMS CONSULTANT**