



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22011332/Kvy3m4	
			Date: 14/03/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SE 9339M	Veh. Inspected	SLV 6509C
	Policy No.	D22MTPV01005355	Coverage (\$)	0.00
	Claim No.	CMTD2204077/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	11/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	KIA CERATO K3 (A)	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	KNAFZ411MJ5757654	Colour	METALLIC RED
	Odometer	148971 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/40 R18	BRIDGESTONE	4 mm
	L/H Front Tyre	225/40 R18	BRIDGESTONE	4 mm
	R/H Rear Tyre	225/40 R18	BRIDGESTONE	4 mm
	L/H Rear Tyre	225/40 R18	BRIDGESTONE	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/11/2022	Inspection Date	11/11/2022
	Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	