REC'D / FILE BY: GQ | REF: AXA CS3/ASM22011337/Gnp3

PRS

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / N/S / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s KENG HOCK MOTOR

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: $-

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBD3551L Yr Regn: - /

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: YAMAHA T135 c.c 135

Colour Black A/C: Insured / Std / NI / NA

Sp.Reading — T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: -

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 80/90-17 PIR

R: // DUN

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	mm	L/Bal.	mm
D.O.A.		D.O.I.	11-11-2022

Survey held at W/S 5:30PM

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	$2000 - $3000
	No GIA provided
21/12/22	submit PRS/ COR range : $2k-$3k

Date/Time, File Pass to? 1) 21/12/22

Date/Time, File Return to? 2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 2

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format: prs

Lump Sum / UPD:

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL