



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                             |                 |                                                             |  |
|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|-----------------|-------------------------------------------------------------|--|
| AXA INSURANCE PTE LTD<br>8 SHENTON WAY #24-01 AXA TOWER<br>SINGAPORE 068811<br>ATTN: LOW GARNET                                        |                                                                                                             |                 | Ref: CS/ASM22011340/Uwp3e2<br>Date: 12/12/2022<br>Code: ASM |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                             |                 |                                                             |  |
| Insured Veh.                                                                                                                           | SCP 3737T                                                                                                   | Veh. Inspected  | SFM 1834P                                                   |  |
| Policy No.                                                                                                                             | GA088496                                                                                                    | Coverage (\$)   | 0.00                                                        |  |
| Claim No.                                                                                                                              | S2M04ELP                                                                                                    | Excess (\$)     | 0.00                                                        |  |
| Assign From                                                                                                                            | LOW GARNET                                                                                                  | Assign Date     | 11/11/2022                                                  |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                             |                 |                                                             |  |
| Make & Model                                                                                                                           | MERCEDES BENZ C180 (A)                                                                                      | c.c             | 1595                                                        |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                                      | Year of Reg.    | 2013                                                        |  |
| Chassis No.                                                                                                                            | WDD2040312A854340                                                                                           | Colour          | SILVER                                                      |  |
| Odometer                                                                                                                               | 83556 KM                                                                                                    | Steering        | IN ORDER                                                    |  |
| Brakes                                                                                                                                 | IN ORDER                                                                                                    | Modification    | SPORTS RIM                                                  |  |
| General                                                                                                                                | GOOD                                                                                                        |                 |                                                             |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                             |                 |                                                             |  |
|                                                                                                                                        | Size                                                                                                        | Make            | Balance                                                     |  |
| R/H Front Tyre                                                                                                                         | 225/45 R17                                                                                                  | FIRENZA         | 6 mm                                                        |  |
| L/H Front Tyre                                                                                                                         | 225/45 R17                                                                                                  | FIRENZA         | 6 mm                                                        |  |
| R/H Rear Tyre                                                                                                                          | 225/45 R17                                                                                                  | FIRENZA         | 6 mm                                                        |  |
| L/H Rear Tyre                                                                                                                          | 225/45 R17                                                                                                  | FIRENZA         | 6 mm                                                        |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                             |                 |                                                             |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.<br>DAMAGES SEE DETAILS.                                                        |                                                                                                             |                 |                                                             |  |
| <b>5. General Information</b>                                                                                                          |                                                                                                             |                 |                                                             |  |
| Accident Date                                                                                                                          | 09/11/2022                                                                                                  | Inspection Date | 11/11/2022                                                  |  |
| Survey held at                                                                                                                         | BLUWEL RENT-A CAR PTE LTD<br>BLK 1 KAKI BUKIT AVE 6<br>BLK C #01-56 AUTOBAY @KAKI BUKIT<br>SINGAPORE 417883 |                 |                                                             |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                             |                 |                                                             |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                             |                 |                                                             |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                                             |                 |                                                             |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                                             |                 | 5 Working Days                                              |  |