



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: HO WINNIE

Ref: CS/ASM22011342/Uqp3e2
Date: 18/11/2022
Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 6423G	Veh. Inspected	SLH 3035X
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S2M04EM6	Excess (\$)	0.00
Assign From	HO WINNIE	Assign Date	11/11/2022

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL HYBRID (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU31211251	Colour	RED
Odometer	105164 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	MICHELIN	6 mm
L/H Front Tyre	215/55 R17	MICHELIN	6 mm
R/H Rear Tyre	215/55 R17	MICHELIN	6 mm
L/H Rear Tyre	215/55 R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/11/2022	Inspection Date	11/11/2022
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**