



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22011345/Aqy3e2	
			Date: 30/01/2023	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBK 5886X	Veh. Inspected	GZ 377T
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2204087/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	11/11/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	NISSAN PICK UP	c.c	2664
	Engine No.	HIDDEN	Year of Reg.	2005
	Chassis No.	JN1AHGD22Z0037721	Colour	SILVER
	Odometer	475112 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	185 R14C	DUNLOP	6 mm
	L/H Front Tyre	185 R14C	DUNLOP	6 mm
	R/H Rear Tyre	185 R14C	DUNLOP	6 mm
	L/H Rear Tyre	185 R14C	DUNLOP	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	09/11/2022	Inspection Date	11/11/2022
	Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	