

(08/11/13) waf

ASS REC. BY: PM

REF:

CC4/LPC 2201346/Rpa3

7092

COE-2028/007

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJK 5147Bat Workshop m/s MOVAof BUKIT MERAHInsured: LPC

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 60K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT - 40KVeh No: SJK 5147B Yr Regn: 2008 10GType: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA CAMRY 2.0 A cc 1998Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 308359 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MR053BK4107035646

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / Rim / STD A/Rim orTyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 10/11/22 D.O.I. 21/11/22Survey held at MOVADes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. Report

1) Date/Time, File Return to?

☐ : Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

2) \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

) S + RS \_\_\_\_\_ SI

) Photos

) Others

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

TOTAL

# ESTIMATE

LONPAC INSURANCE BHD  
300 BEACH ROAD  
17-04/07 THE CONCOURSE  
SINGAPORE 199555

Page : 1  
Veh No : SJK5147B  
Model : TOYOTA CAMRY  
Acc Date : 10-Nov-22  
Incharge : BILLY  
Code : CD0041

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel : (65) 6476 3333  
Fax : (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722  
Tel : (65) 6272 3892  
Fax : (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

No	Description	Qty	U.Price	Amt \$
<u>LIST ITEMS:</u>				
1	BOOT LID <i>lt/</i>	1	\$ 895.00	\$ 895.00
2	BOOT LID HINGE RH & LH <i>?</i>	2	\$ 153.00	\$ 306.00
3	BOOT LID LOGO <i>ne/</i>	1	\$ 65.00	\$ 65.00
4	BOOT LID EMBLEM - CAMRY <i>ne/</i>	1	\$ 58.00	\$ 58.00
5	BOOT LID EMBLEM - 2.0 <i>ne/</i>	1	\$ 48.00	\$ 48.00
6	BOOT LID CHROME MOULDING <i>?</i>	1	\$ 375.00	\$ 375.00
7	BOOT LID REFLECTOR RH & LH <i>X</i>	2	\$ 395.00	\$ 790.00
8	BOOT LID GARNISH <i>?</i>	1	\$ 502.80	\$ 502.80
9	BOOT LID LOCK <i>cut/</i>	1	\$ 380.00	\$ 380.00
10	BOOT LID WEATHERSTRIP <i>ne/</i>	1	\$ 225.00	\$ 225.00
11	TAILLAMP ASSY RH & LH <i>cut/</i>	2	\$ 510.00	\$ 1,020.00
12	TAILLAMP PANEL RH & LH (REPAIR)	2	\$ -	\$ -
13	REAR END PANEL <i>lt/ photo?</i>	1	\$ 605.00	\$ 605.00
14	REAR END PANEL TOP COVER <i>lt/</i>	1	\$ 400.00	\$ 400.00
15	REAR BUMPER <i>cut/</i>	1	\$ 545.00	\$ 545.00
16	REAR BUMPER SCREW CAP LH <i>X</i>	1	\$ 55.00	\$ 55.00
17	REAR BUMPER REINFORCEMENT <i>lt/</i>	1	\$ 395.00	\$ 395.00
18	REAR BUMPER RETAINER RH & LH <i>X</i>	2	\$ 65.00	\$ 130.00
19	REAR BUMPER CLIPS <i>ne/</i>	10	\$ 5.00	\$ 50.00
LIST TOTAL S\$				\$6,844.80
25% DISCOUNT				\$ 1,711.20
				<u>\$ 5,133.60</u>
<u>SPECIAL NET ITEMS:</u>				
1	REVERSE SENSOR <i>nw/</i>	1	\$ 200.00	\$ 200.00
SPECIAL NET TOTAL S\$				<u>\$ 200.00</u>



**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722

Tel: (65) 6272 3892  
Fax: (65) 6270 8314

Co. Reg. 198904033G  
GST Reg. M2-0088864-2

**LABOUR**

- |   |  |                            |
|---|--|----------------------------|
| 1 | TO CUT / WELD REAR END PANEL , KNOCK & STRAIGHTEN<br>TAILLAMP PANELS, REAR FENDERS. REMOVE & REPLACE ACCIDENT<br>PARTS, REALIGN ALL CONNECTION | \$ <del>800.00</del> 600   |
| 2 | SPRAY RAIN BOOT LID, REAR END PANEL, TAILLAMP PANEL,<br>REAR FENDERS, REAR BUMPER.SPARE WHEEL PANEL  | \$ <del>1,000.00</del> 600 |
| 3 | REMOVE & REPLACE LUGGAGE COMPARTMENT INNER TRIM,<br>GARNISH, COVERING  | \$ <del>600.00</del> 40    |
| 4 | REMOVE & REPLACE REVERSE SENSOR & CHECK FUNCTION   | \$ <del>600.00</del> 20    |
| 5 | RUST PROOF AFFECTED AREAS  | \$ 50.00 ✓                 |
|   | LABOUR TOTAL S\$   | <u>\$1,970.00</u>          |

NON-TAX AMOUNTS

\$7,303.60

GST @ 7%

\$511.25

AMOUNT DUE

\$7,814.85

\_\_\_\_\_  
Customer's Signature/Co. Stamp

\_\_\_\_\_  
MOVA AUTOMOTIVE PTE LTD

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Rame*  
*Hp 90010068*  
*6 days*  
*4/8*  
*21/11/22 @ 1210*  
*Reg after paint*

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	10/11/2022 14:18 (SGT)
Reported by	Both
Date of Accident	10/11/2022 08:40 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PIE AFTER ENG NEO AVENUE TOWARDS LORNIE HIGHWAY
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK5147B
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	CHIEW CHENG SAN
NRIC No	SXXXX709Z
Email Address	CS2005SG@GMAIL.COM
Mobile Phone No	(Phone) +65-96277183
Alternative Phone No	-

## VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Camry
Variant	2.0 AUTO ABS AIRBAG
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1998

## INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5039469312-13

## DRIVER

Name of Driver	CHIEW JIA HUI
NRIC No	SXXXX200J
Date Of Birth	06/11/1997
Occupation	Indoor

Date Of Driving Pass .....  
Driving experience .....  
Gender .....  
Mobile Number .....  
Alt. Phone Number .....  
Email Address .....  
Address .....  
Address complement .....  
Postcode .....  
Is the driver the policyholder? .....  
If No, Relationship of the Driver with the Insured .....  
Does Driver Own Other Vehicles? .....  
Vehicle Registration Number of Other Vehicle Owned by Driver .....  
Insurance Company of Other Vehicle Owned by Driver .....

10/11/2018  
4 YEARS  
Female  
(Phone) +65-91862065  
-  
CHIEWJIAHUI2@GMAIL.COM  
48 TOH TUCK ROAD #07-05  
-  
596739  
No  
Child  
No  
-  
-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....  
Weather Conditions .....  
Road Surface .....

Collision - Head to Rear  
Clear  
Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? .....  
Number of vehicles involved in the accident .....  
Was anybody injured in the Accident? .....  
Was any injured conveyed to hospital by ambulance? .....  
Was any other vehicle or property damaged? .....  
Number of Passengers (Including Driver) .....  
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? .....  
Translator's name .....  
Translator's ID .....  
Translator's phone number .....  
Translator's email .....  
Original language used in the statement .....

No  
2  
No  
-  
Yes  
2  
No  
-  
-  
-  
-  
-

#### PASSENGER 1

Name .....  
Gender .....

CHIEW CHENG SAN  
Male

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? .....  
Was notice of intended Prosecution given? .....  
If yes, against whom? .....

No  
No  
-

#### CIRCUMSTANCES OF ACCIDENT

#### PLS REFER TO SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment? .....  
Was there any video captured by Car Camera? .....  
Reasons for not uploading a video of the accident .....

Yes  
Yes  
EMAIL TO INSURANCE

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number .....  
Vehicle Manufacturer .....  
Vehicle Model .....

GBC2333L  
Mitsubishi  
Fuso





Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	SURESH A/L CHANDRA SAIGARAN
Passport No/FIN	GXXXX218T
Contact Number	(Phone) +65-83477408
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1



# SKETCH PLAN


## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time: 10.22 Driver's Signature (if driver is not the policyholder) / Date: 10/11/22  
 Sketch Plan: NEO AVE EXIT Time: 10:22 am

Witnessed by Reporting Centre Personnel  
 (Name as in NRIC/ID card)

LORNE HIGHWAY



A: SJK S147B  
 B: GBC 2333L

TRAFFIC FLOW  
 →

SINGAPORE AIRLINES  
 COUNTRY CLUB

1





Describe Circumstance of the Accident

VEHICLE NO: **STK 5147 B** ACCIDENT DATE & TIME: **10 NOV 2022**  
 CONTACT NUMBER: **91862065** E-MAIL: **CHIEW JIAHUI2@GMAIL.COM**  
 LOCATION: **PIE AFTER ENG NEO AVE TOWARDS LUNIE HWY**

ROAD CONDITIONS: **DRY, HEAVY MORNING TRAFFIC MOVING AT SLOW SPEED WITH OCCASSIONAL STOPPAGE.**  
**DRIVING ALONG STRAIGHT PATH ON SLOW MOVING TRAFFIC, FOLLOWING CAR IN FRONT. STOPPED CAME TO A SLOW HAUT WHEN VEHICLE IN FRONT STOPPED MOMENTARILY. WAS HIT FROM BEHIND BY VEHICLE B.**

**CLAIM 3RD PARTY**  
~~AGREED ON PRIVATE SETTLEMENT WITHOUT INSURANCE CLAIM~~

NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE A 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION.

PLEASE STATE: ☐ CLAIM OWN POLICY ☐ CLAIM THIRD PARTY ☐ CLAIM ODTP AT OTHER WORKSHOP ☐ REPORTING ONLY

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

**16.22 10/11/22**

Driver's Signature (if driver is not the policyholder) / Date & Time

**10.22 am 10/11/22**

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)





> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Singapore NRIC

Owner ID: 709Z

Vehicle No.: SJK5147B

Vehicle to be Exported: No

Intended Deregistration Date: 22 Nov 2022

Vehicle Make: TOYOTA

Vehicle Model: CAMRY 2.0 AUTO ABS AIRBAG

Primary Colour: Silver

Manufacturing Year: 2008

Engine No.: 1AZE117112

Chassis No.: MR053BK4107035646

Maximum Power Output: 108.0 kW (144 bhp)

Open Market Value: \$25,403.00

Original Registration Date: 24 Oct 2008

First Registration Date: 24 Oct 2008

Transfer Count: 0

Actual ARF Paid: \$25,403.00

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date:

PARF Rebate Amount: \$0.00

COE Expiry Date: 23 Oct 2028

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

PQP Paid: \$32,279.00

COE Rebate Amount: \$19,107.00

Total Rebate Amount: \$19,107.00

The information contained herein is correct as at 22 Nov 2022

OK



# Toyota Camry 2.0A (COE till 11/2028)

## Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

<b>Price</b>	<b>\$61,800</b>		
<b>Depreciation</b> ?	\$10,310 /yr	<b>Reg Date</b>	19-Nov-2008 (5yrs 11mths 27days COE left)
<b>Mileage</b>	N.A.	<b>Manufactured</b> ?	2008
<b>Road Tax</b> ?	\$1,694 /yr	<b>Transmission</b>	Auto
<b>Dereg Value</b> ?	\$19,255 as of today (change)	<b>OMV</b> ?	\$25,403
<b>COE</b> ?	\$32,121	<b>ARF</b> ?	\$25,403
<b>Engine Cap</b>	1,998 cc	<b>Power</b>	108.0 kW (144 bhp)
<b>Curb Weight</b> ?	1,530 kg	<b>No. of Owners</b> ?	2
<b>Type of Vehicle</b>	Luxury Sedan		

## Features

View specs of the Toyota Camry (2006-2012)