

CS / AG / 22011347 / TVY3

2028 O.A.

Veh No: FRD8407 Yr Regn: 2008, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha WR250 cc 250.

Colour Blue A/C: Insured / Std / NI / NA

Sp. Reading — T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JY A1/6202000001667.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NJ / S/Rim / STD A/Rim or

Tyre Size: F: 110A/RK17

R: 150/160 R17

150/00117

ES/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO / YOKO OF

Front _____ Rear _____

R/Bal. 5 mm 100 R/Bal. 5

_____ /Bal _____

3/11/2022

Survey held at: 14C (1916) 17/12/22

Des. of Damages : Fit / Rear / O/S / N/S / U/G / Rooftop- or

The U/C / Chassis frame / Body Structure affected due to collision.

Days Of Repair: 3

☐ : Final Report

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

Lampa Bern / E.E.H. / \$4000

☐ : Interview (\$

☐ : Tech. Invs (\$)

☐ : Weekend (S)

Photos

Others

Category	Percentage
1. Total	100%
2. ...	...
3. ...	...
4. ...	...
5. ...	...
6. ...	...
7. ...	...
8. ...	...
9. ...	...
10. ...	...
11. ...	...
12. ...	...
13. ...	...
14. ...	...
15. ...	...
16. ...	...
17. ...	...
18. ...	...
19. ...	...
20. ...	...
21. ...	...
22. ...	...
23. ...	...
24. ...	...
25. ...	...
26. ...	...
27. ...	...
28. ...	...
29. ...	...
30. ...	...
31. ...	...
32. ...	...
33. ...	...
34. ...	...
35. ...	...
36. ...	...
37. ...	...
38. ...	...
39. ...	...
40. ...	...
41. ...	...
42. ...	...
43. ...	...
44. ...	...
45. ...	...
46. ...	...
47. ...	...
48. ...	...
49. ...	...
50. ...	...
51. ...	...
52. ...	...
53. ...	...
54. ...	...
55. ...	...
56. ...	...
57. ...	...
58. ...	...
59. ...	...
60. ...	...
61. ...	...
62. ...	...
63. ...	...
64. ...	...
65. ...	...
66. ...	...
67. ...	...
68. ...	...
69. ...	...
70. ...	...
71. ...	...
72. ...	...
73. ...	...
74. ...	...
75. ...	...
76. ...	...
77. ...	...
78. ...	...
79. ...	...
80. ...	...
81. ...	...
82. ...	...
83. ...	...
84. ...	...
85. ...	...
86. ...	...
87. ...	...
88. ...	...
89. ...	...
90. ...	...
91. ...	...
92. ...	...
93. ...	...
94. ...	...
95. ...	...
96. ...	...
97. ...	...
98. ...	...
99. ...	...
100. ...	...

SJE :

Date of Survey :

Contacts :

Vehicle Nos : FBD 840Y

Model : YAMAHA WR250X

Year :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front headlamp complete assy	1	\$ 675.50	\$ x nn 675.50
2	Front headlamp outer cowling	1	\$ 185.30	\$ cut 185.30
3	Mirror assy LH	1	\$ 167.20	\$ cut 167.20
4	Front clutch lever LH	1	\$ 276.20	\$ cut 276.20
5	Front handle bar	1	\$ 295.00	\$ bt 295.00
6	Front handle bar grip	2	\$ 62.80	\$ x nn 125.60
7	Front fork assy (set)	1	\$ 2,262.50	\$ 1000 2,262.50
8	Front fender	1	\$ 185.00	\$ cut 185.00
9	Front brake disc	1	\$ 325.20	\$ bt 325.20
10	Front wheel rim	1	\$ 574.30	\$ x nn 574.30
11	Front side stand	1	\$ 125.40	\$ x nn 125.40
12	Front signal LH	1	\$ 136.20	\$ nn 136.20
13	Front side fairing LH	1	\$ 243.60	\$ cut 243.60
14	Rear side top fairing LH	1	\$ 217.40	\$ cut 217.40
15	Front wheel bearing	2	\$ 25.00	\$ ne 50.00
16	Pillion foot rest LH	1	\$ 167.40	\$ x nn 167.40
17	Rear left side cowling cover	1	\$ 195.00	\$ de 195.00
18	Rear Signal lamp LH	2	\$ 145.00	\$ x nn LH 290.00
19	Front inner cowling LH	2	\$ 252.60	\$ de 505.20
20	Front fork stem	1	\$ 376.40	\$ x nn 376.40
21	Front number plate	1	\$ 30.00	\$ ne 30.00

10% - 3956.30
3560.67

Parts Sub Total : \$ 7,408.40
Discount 10% : \$ 740.84
PARTS TOTAL : \$ 6,667.56

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front fork oil	1	\$ 45.00	\$ ne 45.00
2	Front rim	1	\$ 570.30	\$ de 480 570.30
3	Stickers	1	\$ 153.00	\$ ne 153.00
4	Helmet	1	\$ 565.80	\$ cr 450 565.80

1128

SPECIAL NETT TOTAL : \$ 1,334.10

Nos.	LABOUR	S\$
1	Workmanship	\$ 300 600.00
2	Spray painting	\$ 200 600.00
3	Electrical	\$ 30 80.00
4	Front wheel alignment	\$ 30 50.00
		\$ 560

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

LABOUR TOTAL : \$ 1,330.00

PARTS TOTAL : \$ 6,667.56
SPECIAL NETT TOTAL : \$ 1,334.10
LABOUR TOTAL : \$ 1,330.00
TOTAL : \$ 9,331.66

Deduct 20% : \$ 1,866.33

3560.67
1128
560
5248.67
1/5 \$ 4200
3 days #
Tanjun 1749544
w/ 14/12/22
L/S Kuning after repair
Tanjun e Inhabits van
3 days