

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Re	f: CS/AGI22011347/Tvy3e2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	te: 09/06/2023	
			Co	de: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMA 8752B	Veh. Inspected	FBD 840Y	
	Policy No.	P10377782R02	Coverage (\$)	0.00	
	Claim No.	C10018449/JT	Excess (\$)	0.00	
	Assign From	SALIZAWATI HAIZAR	Assign Date	11/11/2022	
2.	. Vehicle Particulars & Condition				
	Make & Model	YAMAHA WR250X	c.c	250	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	JYADG202000001667	Colour	BLUE	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	110/70 R17	BRIDGESTONE	5 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	150/60 R17	BRIDGESTONE	5 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	03/11/2022	Inspection Date	14/12/2022	
	Survey held at	MS CAR AUTO PTE LTD			
		8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Days of Repair			

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: