Company & GST Registration No. 200616038C

2 Kaki Bukit Avenue 2 #01-17/#01-18 /Heavy Vehicle #01-08/Spray Painting #02-27

Kaki Bukit Autohub Singapore 417921

Tel: 68420051

Fax: 67410510

Email: sales@n51.com.sq

Our Ref:

SJY 3030 T

Your ref:

SLD 1045 B

11 November 2022

AUTO & GENERAL INSURANCE (S) PTE LTD

SINGAPORE SHOPPING CENTRE 190 CLEMENCEAU AVENUE #03-01 SINGAPORE 239924 Attn: Motor Claims Department

Dear Sir/Madam.

NAME OF CLAIMANT: KHAIRUDIN BIN KAMARUDI

VEHICLE NUMBER: SJY 3030 T

YOUR INSURED VEHICLE NUMBER: SLD 1045 B ACCIDENT ON 10 NOV 2022 AT ABOUT 17:10 HOURS ALONG AYE TWDS CITY AFTER JURONG TOWN HALL

We refer to your email/fax dated **11 Nov 2022** informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment **LKK of Adrian Ling** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub 2 Kaki Bukit Avenue 2 #01-18 Singapore 417921

Contact Person:

6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!

Appointed surveyor:

(Name & Signature):

Date & Time of Inspection: