



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22011348/Avy3e2 Date: 02/12/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLD 1045B	Veh. Inspected	SJY 3030T	
Policy No.	P10170433R03	Coverage (\$)	0.00	
Claim No.	C10018570/JY	Excess (\$)	0.00	
Assign From	SALIZAWATI HAIZAR	Assign Date	11/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT	c.c	1317	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GK31333524	Colour	GREY	
Odometer	146145 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/50 R16	MICHELIN	6 mm	
L/H Front Tyre	205/50 R16	MICHELIN	6 mm	
R/H Rear Tyre	205/50 R16	MICHELIN	6 mm	
L/H Rear Tyre	205/50 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/11/2022	Inspection Date	14/11/2022	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		