ASS. REGOBY: Steve 1 (S) FC/D209129/ Eng3-1.	
PRS . ASSI	GNMENT
From: Date:	Veh No: FB3 8681H Yr Regn; 23/8/21
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD I THI WS ITP RES I OD RES I EVA I INV I MV	Truck / Traller or
To Inspect Vehicle No:	Make: 1-1017 (19 70129 c.c 330
et Workshop m/s	Colour Red A/C: Insured / Std / NI / NA
ol	Sp.Reading T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: MUHNFO97XM5019388.
Claims No.	Gen. Cond: Good Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inoyde) / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim (STD A/Rim or
	Tyre Size: F: 11/0/70-14
(Policy Condition)	. R: 130 70-15
Remark: The veh had commenced its N/S O/S	(BS) DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM! /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value;	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal, R/Bal. W mm
GIA / PR Seen: Consistent? : Yes or No	UBal. WBal. mm
Est Repairs: 4 days Res.: Yes or No	D.O.A. 7/18/11
Lum Sum: % 3 Val.: Yes or No	Survey held at Speed Way
CA REV REP. 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehlcle: IŅ / OU	
Date: Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision.	
Date/Time Action/Instruction Repair vange UK-SK	
	LY JAVE
22/09/22 submit PRS report- repair range:\$4k-\$5k and 4 days	
market value: 20k (est)	
15/1/22 Submit LS \$8300, 4 days. (Red \$3000, 27%)	
OsterTime, File Pass to? 15/111 Type int	Days Of Repair: 4
15/11 Typist : Final Report : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to7	. Transportation:
2) Add F	ee: : Site Insp (\$)s +Rssi
	:Interview (\$) Photos
Reparts Format : Pre TP	:Tech, Invs (\$) Others
Lump & mm (4.5.4. († 8300 .)	:Weelland (*)
	TOTAL
	and the second s
	· · · · · · · · · · · · · · · · · · ·