



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
KELVIN CHIA PARTNERSHIP 6 TEMASEK BOULEVARD 29TH FLOOR SUNTEC TOWER FOUR SINGAPORE 038986			Ref: CS/LAW22011355/Kqy3m4	
			Date: 04/04/2023	
			Code: L041	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	GBG 6027Z	Veh. Inspected	FBM 267E	
Policy No.	A 29022516 MKC	Coverage (\$)	0.00	
Claim No.	SS.sm.2021000388.MSIG	Excess (\$)	0.00	
Assign From	VITHY	Assign Date	04/10/2022	
2. Vehicle Particulars & Condition				
Make & Model	KAWASAKI Z1000 (M)	c.c	1043	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JKAZRT00HJA001465	Colour	METALLIC BLACK/ GREY	
Odometer	50290 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70 ZR17	BRIDGESTONE	3 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	190/55 ZR17	BRIDGESTONE	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	21/01/2020	Inspection Date	14/11/2022	
Survey held at	11 KAKI BUKIT CRESCENT SINGAPORE 416241			
Repairer	REVOLOGY BIKES PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	