

REF: CS/LAW22011355/Kqy3

Special Instruction:

ASSIGNMENT (Office)

From (Person): Vithy of KELVIN CHIA PARTNERSHIP Date/Time: 04/10/2022  
Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

LS : \$ 18000 / 10 DAYS

Third Parties:

Claimant:

Surveyor: PRUDENT ADJUSTORS  
SERVICES

Workshop: REVOL

Workshop: **REVOLOGY**

OD TP Re-inspection / Evaluation

To Inspect Vehicle No: FBM 267E Insured: GBG 6027Z

at Workshop m/s **REVOLOGY**

of 11 Kaki Bukit Crescent Singapore 416241

Policy No: \_\_\_\_\_ Claim No: **SS.sm.2021000388.MSIG**

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 21/01/2020  
(Client's Record)

(Client's Record)

D.O.A. 21/01/2020

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT

H.O.D. Endorsement/Date:

Date/Time: \_\_\_\_\_ Confirmed with \_\_\_\_\_ Final Fig \_\_\_\_\_, \_\_\_\_ days (Red S \_\_\_\_/\_\_\_\_%; Original! \_\_\_\_ days)

Date/Time: 06/03/23 Submit ~~Final Fig~~ LS \$11650, 6 days (Red \$ 6350 / 35 %; Original 6 days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	
--	--

**Para(3) : Nett Value**

Market Value : \_\_\_\_\_

Salvage Value : \_\_\_\_\_

Nett Value : \_\_\_\_\_

Inspected/  
Evaluated by:

Fee Charged:

Basic &amp; Add

Transport

## Photos

Others

Total

Date: \_\_\_\_\_

1) Date/Time 06/03/23 File Pass to Typist

2) Date/Time

File Return to

3) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

#### 4) Date/Time

File Return to

5) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

6) Date/Time

File Return to