

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



AUTOMOBILE INSPECTION REPORT					
INCOME INSURANCE LTD			Ref:	NS/INC22011375/Tnce2	
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	08-12-2022 INC4	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SNE 9542B	Veh. Ir	spected	SHD 7136E
	Policy No.		Covera	age (\$)	0.00
	Claim No.	MT/1191315-003	Exces	s (\$)	0.00
	Assign From		Assign	n Date	03/10/2022
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI I40	c.c		1685
	Engine No.	HIDDEN	Year o	f Reg.	2016
	Chassis No.	KMHLB41UMHU096292	Coloui	•	BLUE
	Odometer	800888	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	205/60 R16	WEST	_AKE	6 mm
	L/H Front Tyre	205/60 R16	WEST	_AKE	6 mm
	R/H Rear Tyre	205/60 R16	WEST	_AKE	6 mm
	L/H Rear Tyre	205/60 R16	WEST	_AKE	6 mm
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date 01/10/2022 Inspection Date 03/10/2022				03/10/2022
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD  59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				