

Our Job Ref No : 305532072 ComfortDelGro Engineering Pte Ltd Date 13.10.2022 59 Loyang Drive Singapore 508969 **FINALIZATION FORM** LKK Fax: **TAUFIKH** Attn : Vehicle Reg No. : SHA388G 28.09.2022 The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-Z The repair job shall bill to: INCOME GX379Z 2. The finalized amount shall be: Spare Parts after List discount (a) (b) Labour Charges Total for Part-By-Part Repair Cost (c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost \$1,450.00 3. Estimated normal period for repairs: 2 working days. 4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days 5. Thank you for your assistance. We confirm the estimates and finalized amount Signature: Signature: Name CHIANG Name Tel -: 62148314 Date Fax : 65468156 For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	•	N		
3. Survey Fees	1¥0	524		
4. LTA Search Fee	\$7.49/\$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Överrun				

Remarks:					