

AS-S. REC-BY: Touy


REF: CS/ +M 1.22011388/Tuy 3.

ASSIGNMENT

From: _____ Date: _____
Estimated cost: _____
OD / TP / VS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Report _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS WP
Date: _____ Person Contacted: UMTS Vehicle: IN / OUT

Veh No: SMD 7314H Yr Regn: 2018 / Dec
Type: M.Car / M.Cycle / Bus / Van / Lorry / 7 / Prime Mover /
Truck / Trailer or
Make: Hyundai C.C. 1580
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 419515 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: UM4C 851 CUREY 122044
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: NR / S/Rim / STD A/Rim or
Tyre Size: F: 195/65R15
R: _____
BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Westlake
Front Rear
R/Bal. 0 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.L. 14/11/22
Survey held at Conquest Lagoon
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frd o/s
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report
1) ☐ : Final Report
Date/Time, File Return to?

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____
Transportation: _____
S + RS _____ SI _____
Photos _____
Others _____

Rep. Form: _____
Lum. Sum / I.B. : _____

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)59 Loyang Drive
Singapore 508969
Tel: 6214 8300**TP INSURER:**
CTPL**Tokio Marine Insurance Singapore Ltd (HQ)**

CLB

Singapore

LKK-

PARTICULARS OF CLAIMClaim Type: THIRD PARTY
Policy No:
Vehicle Reg. No.: SHD7314H
Party At Fault: UNKNOWNRef. No:
Date of Loss: 11/11/2022
Driveable? NOMake/Model: HYUNDAI IONIQ HYBRID, 1.6 GLS
DCT (A)
Vehicle Colour: BLUE
Engine No: G4LEJU132632
Odometer: 0 KMVehicle Reg. Date: 04/12/2018
Gen Condition: EXCELLENT
Chassis No: KMHC851CVKU122044Paint Type:
List Item Discount: 20.00 %
Total Loss? NO
Est. Duration of Repair
(day) 4

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS**Amount**

Parts	3,843.72
Miscellaneous Items	11.00
Labour	1,700.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$)	5,554.72
+ GST 7.00% (S\$)	388.83
Nett Amount (S\$)	5,943.55

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 14 Nov 2022)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD7314H/14/11/2022 10:29**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER	20.00	0.00	le ✓ *481.10 FL
2	1		*FRT BUMPER UPPER MOULDING	20.00	0.00	X *368.50 FL
3	10		*FRT BUMPER CLIPS	20.00	0.00	na ✓ *22.00 FL
4	1		*FRT FENDER RH	20.00	0.00	af ✓ *588.80 FL
5	1		*FRT FENDER BLUE-DRIVE RH	20.00	0.00	na ✓ *26.60 FL
6	1		*FRT WHEEL CAP RH	20.00	0.00	cut ✓ *346.40 FL
7	1		*HEADLAMP RH	20.00	0.00	? *2,110.30 FL
8	1		*DAYLIGHT RH	20.00	0.00	X *642.50 FL
9	1		*DAYLIGHT GRILLE RH	20.00	0.00	X *93.45 FL
10	1		*FRT FENDER ADVERTISEMENT STICKER RH	0.00	0.00	na ✓ *100.00 F

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)	4,779.65
- List Item Discount on L Items (\$\$)	935.93
Total Parts (\$\$)	3,843.72

ComfortDelGro Engineering Pte Ltd/SHD7314H/14/11/2022 10:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	PANEL BEATING	New	350	800.00
2	SPRAY PAINTING	New	500	700.00
3	TUFF KOTE	New	30	40.00
4	CHECK LIGHTINGS	New	30	40.00
5	WHEEL ALIGNMENT	New	80	120.00

Gross Labour Cost (S\$)

1,700.00

ComfortDelGro Engineering Pte Ltd/SHD7314H/14/11/2022 10:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tan Kah 97415449
up 14/4/22 430pm
c/s rising after repair
for MIC Insurance
2-3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
329 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 768732

Date/Time: 14.11.2022 10:15

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5230253

JC NO305536359


COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (P) (O)	REGN NO: SHD7314H	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL IONIQ(G2)	DATE/TIME IN 14.11.2022 09:00
	YR OF MANU 04.12.2018	TARGET DATE
	CHASSIS CODE KMHC851CVKU122044	COMPLETION DATE/TIME:

Accident Date: 11.11.2022
DURATION: 3P 11.11.2022

JOB DESCRIPTION

NO LABOR CODE

DESCRIPTION



TO BE PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Payment Slip

Exit Pass

SHD7314H

LIMITS

Vehicle No.:

SHD7314H

Service Advisor

Signature/Date

Name of Service Advisor

Date

to be kept by Security Guard