	LO 11402/Ruy3 SSEH SSIGNMENT (OK-2016/SEP
<u> -</u> nva	
From: Date: Estimated Cost:	Veh No: GBC 284R Yr Regn: 2016 1007 Type: M.Car / M.Cycle / Bus / Vap/ Lorry / Taxl / Prime Mover /
	Truck / Trailer or
OB/TP/WS/TP RES/OD RES/EVA/INV/MV	43.40
To Inspect Vehicle No: LBC 2849R	Make: Toyota HIACG NAWAR C.C 2982
of 160 SIN MINL MATUR- UR	Colour WHIE A/C: Insured / Std / NI / NA
	Sp.Reading 495171 T/Radio: Insured / Std / NI / NA
nsured: SAL	Eng/No:
Policy No.	C/No: JTPHT621100078685.
Claims No.	Gen. Cond: Good / Fair Poor / Burnt
Sum Insured: Excess: The	Steering: Morder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: brorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil 1 S/Rim / STD A/Rim or
	Tyre Size: F: 195R157
(Policy Condition)	R: 4.
	BS DUN EXNOVA GY FS LIZA MIC OHTSU PIR SUMI
repair at the time of inspection.	TOYO/YOKO or
2014	
· · · · · · · · · · · · · · · · · · ·	R/Bal. L mm R/Bal. L mm
DAC Accident Rport: Consistent? : Yes or No	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 06/11/22 D.O.I. 14/11/22
Lum Sum: % 3 Val.: Yes or No	Survey held at VINS AND
CA I (REA J REP. / 24 HRS	Des. of Damages Fin / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN/O	OUT COUT
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction REPAM 4MIT 21K	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
Date/Time, File Pass to? : Preli. Report 1) : Final Report	Days Of Repair:
. Freit. Report	Resurvey No. of Trip: Survey Fee:
1) : Final Report	Resurvey No. of Trip: Survey Fee: Transportation:
1) : Final Report Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee: Transportation: Section 1. Step 1
1) : Final Report Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee: Transportation:

the said a shelpful a sure and

Vin's

Vin's Motor Pte Ltd 160 Sin Ming Drive #03-03 Sin Ming Autocity Singapore 575722 Tel: 6453 2121 Fax: 6459 9795 GST Registration No. 199906067G

Estimated Cost of Repair

Attention To

GREAT AMERICAN
INSURANCE COMPANY

3 Temasek Avenue #16-01 Centennial Tower Singapore 039190 **Claim Details**

Case Ref. No.

OD/112022/5759

Date : 07-11-2022 Accident Date : 06-11-2022

Vehicle Details

Make & Model

Toyota HIACE MANUAL

Chassis No

JTFHT02P100078685

Registration No : GBC2849R

S/N	Description ,	Qty	Amount (S\$)
1	FRONT BONNET 5	1.00	\$470.00
2	BONNET RH HINGE X	1.00	\$30.00
3	BONNET LH HINGE 🗡	1.00	\$30.00
4	BONNET EMBLEM NA	1.00	\$40.00
5	BONNET LOCK by	1.00	\$60.00
6	RH HEADLAMP CM	1.00	\$410.00
7	LH HEADLAMP CA	1.00	\$410.00
8	FRONT GRILLE BASE CM	1.00	\$80.00
9	FRONT GRILLE CM	1.00	\$330.00
10	FRONT BUMPER de	1.00	\$300.00
11	FRONT BUMPER TOP BEAM 51	1.00	\$110.00
12	FRONT BUMBER REINEORCEMENT 54	1.00	\$250.00
13	FRONT BUMPER CENTER LETTER GRILLE & CA	1.00	\$130.00
14	FRONT BUMPER RH SIDE RETAINER X	1.00	\$80.00
15	FRONT BUMPER LH SIDE RETAINER X	1.00	\$80.00
16	FRONT SUPPORT PANEL	1.00	\$240.00
17	BRACE PANEL LA	1.00	\$30.00
18	AIRCON CONDENSER 14/	1.00	\$920.00
19	AIRCON CONDENSER FAN MOTOR	1.00	\$850.00
20	AIRCON CONDENSER FAN BLADE	1.00	\$90.00
21	AIRCON CONDENSER FAN COWLING 7	1.00	\$220.00
22	RADIATOR 31/	1.00	\$1,400.00
23	RADIATOR FAN MOTOR X	1.00	\$850.00
24	RADIATOR FAN BLADE 7 X	1.00	\$90.00
25	RADIATOR FAN COWLING 77	1.00	\$220.00
26	INTER COOLER & ST	1.00	\$940.00
27	INTER COOLER INLET HOSE X	1.00	\$210.00
28	INTER COOLER OUTLET HOSE X	1.00	\$190.00
29	INTER COOLER BRACKET	1.00	\$120.00 \$100.00
30	INTER COOLER AIR DUCT X	1.00	\$100.00



Vin's Motor Pte Ltd 160 Sin Ming Drive #03-03 Sin Ming Autocity Singapore 575722 Tel: 6453 2121 Fax: 6459 9795 GST Registration No. 199906067G

31	SPARE TANK X	1.00	\$250.00
		Margin: 10%	\$9,530.00 \$953.00
			\$10,483.00
32	FRONT NO. PLATE 11	1.00	\$40.00 35
33	COOLANT A	1.00	\$80.0050
34	COMPANY STICKER **/	1.00	\$500.00 200
	TO REFILL AIRCON GAS	1.00	\$150.00 100
35	TO REMOVE AND REFIX DASHBOARD	1.00	\$380.00
36	TO REPAIR DAMAGES	1.00	\$980.00 700
37 38	TO SPRAY PAINTING	1.00	\$880.00 400
		Subtotal w/o GST:	\$13,493.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- This party survey is on a "Without Prejudice" basis
- . No degal modification(s) is allowed
- Carolem in item(s) must be a surveyed and is a eject to final approval from insurance Company

Acknowledged by Repairer

Sic wire:

Hp 90010068

b days

4/1

EXCESS: TRA

Rever

Rever

Resury after report

14/11/22 P 1510



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process

2. This Form must be completed by the Policyholder and/or the Actual Driver

2. This Form must be completed by the Policyholder and the Course and the Policyholder and the Course as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

4. The issue and acceptance of this Form by institution of policy manifest of the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Reported by Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

07/11/2022 15:53 (SGT) Driver 06/11/2022 14:30 (SGT) Singapore PASIR RIS ST 11 Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

GBC2849R

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No **Email Address** Mobile Phone No Alternative Phone No

Yes CLEAR CHANNEL SINGAPORE PTE LTD 2XXXXX555H kwangyang.tey@clearchannel.com.sq (Phone) +65-96575629

VEHICLE PARTICULARS

Manufacturer Model Variant your vehicle?

Exact purpose for which vehicle was being used at time of Are you claiming under your own insurance policy for repair to Vehicle Category Transmission

INSURANCE COMPANY

CC

Name of Insurance Company Policy Number / Cover Note Number

Name of Driver NRIC No Date Of Birth Occupation

Lump Sum / I R I. /c

DRIVER

Toyota HIACE MANUAL

Employment

Yes Goods vehicle Manual 2982

Great American Insurance Company MT20211796

MOHAMED FAIID BIN MOHAMED ALI SXXXX586A 13/05/1972 Outdoor

Accident report SV1022B70001

Page 1 of 16

Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address complement Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Other Vehicle Owned by Driver

fightclub1305@gmail.com APT BLK 139 PASIR RIS STREET 11 #07-201 510139 No **Employee** No

28/06/1993

Male

29 YEARS AND 5 MONTHS

(Phone) +65-87578924

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Does Driver Own Other Vehicles?

Type of Accident Weather Conditions Road Surface

Collision - Change/cross lane Raining Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement

DETAILS OF POLICE ACTION

Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Yes Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Name of Driver Contact Number

SJP9807C

Private car AFIQ

(Phone) +65-92716117

Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

SHETCH PLAN

SKETCH PLAN

IMPORTANT NOTICE

i. Figure, report introstly the domain of the Antidomital assence the Law Spicials. to a consequent to a regarded as the proportion of property and a second

6. Any laise reporting may be referred to the Traffic Police Department to investigation

Concernment the property flavor or a result of PTPA:

Skille 1713. A: GBC 2849R 3: SJP9803C

.1 . 2 77

Describe Circumstance of the Accident

On 6/11/22 at around 1430hrs. I was driving at along Pasir ris st 11. All of a sidden vehicle B(SJP9807L) Changed lane from my left lane honce we both vehicles collect and damaged on my fant portan of my vehicle.

Undicator

As directly as a real and a service as

FAL

Duntered governor stansactions

Sai.

Allorsted C. Reporting Quarter on Water as a NOTE Diction

. 30 0

Accident report SV1022B7000

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company	
Owner ID: /ehicle Details	555H	
/ehicle No.:	GBC2849R	
/ehicle to be Exported:	No	
ntended Deregistration Date:	09 Nov 2022	
/ehicle Make:	TOYOTA	
/ehicle Model:	HIACE MANUAL	
Primary Colour:	White	
Manufacturing Year:	2011	
Ingine No.:	1KD2114047	
Chassis No.:	JTFHT02P100078685	
Maximum Power Output:	-	
Open Market Value:	\$25,820.00	
Original Registration Date:	07 Oct 2011	
	07 Oct 2011	
First Registration Date: Fransfer Count:	0	
Transfer Count: Actual ARF Paid:	\$1,291.00	
Actual ARF Paid: Intended PARF Rebate Details		
PARF Eligibility:	No	
PARF Eligibility Expiry Date:		
PARF Rebate Amount:	\$0.00	
Intended COE Rebate Details		
COE Expiry Date:	30 Sep 2026	
COE Category:	C - Goods Vehicle & Bus	
COE Period(Years):	5	
PQP Paid:	\$19,586.00	
COE Rebate Amount:	\$15,244.00	
Total Rebate Amount:	\$15,244.00	
	e can only be for a 5-year period, subject to the statutory lifespan (if applicable	1 641

The information contained herein is correct as at 07 Nov 2022

Toyota Hiace 3.0M (New 5-yr COE)

Overview

Financial

Accessories

Similar

Research

Photos

Мар



YOUR FIRST CHOICE AUTOMOTIVE SERVICE PROVIDER



Price	\$45,000	Lifespan ()	26-Sep-2032
Depreciation (2)	\$9,150 /yr	Reg Date	27-Sep-2012 (5yrs COE left)
Mileage	N.A.	Manufactured (2012
Road Tax (7)	N.A.	Transmission	Manual
Dereg Value 🕜	N.A.	Fuel Type	Diesel
COE	N.A.	OMV	\$25,820
Engine Cap	2,982 cc	ARF()	\$1,291
Curb Weight	1,780 kg	No. of Owners	2