

CS/11/151 Wof

ASS. REC. BY: NAME

REF:

CS/EH/2201/405/RVg3

354m

ASSIGNMENT

COB-2024/001

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XB 9639Dat Workshop m/s WAH HONG MOTORof 38, TOL HUNG RD, TST EAST #01-57Insured: YP 3644S E91

Policy No. DMCG22008419

Claims No. CDMCG22002419

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

1pm

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 20K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: XB 9639DYr Regn: 2005 / Jun

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

GARBAGE TRUCKMake: MITSUBISHI FUSITC.C. 11945Colour: W33 1TG

A/C: Insured / Std / NI / NA

Sp. Reading: 444108

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: F4517JA00581

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 295/80R22.5R: DP

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

UNIRUN

Front

Rear

R/Bal. 8 mmR/Bal. 8/8 mmL/Bal. 8 mmL/Bal. 8/8 mmD.O.A. 10/11/22D.O.I. 21/11/22Survey held at WAH HONG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 14K

15/12/22 Lump Sum \$6500 confirmed by email (Red 4476.50, 40%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 19/12/22-typist

Days Of Repair: 6Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS SI

Photos

Others

Report Format : Merimen

Lump Sum / I.B.I.: (\$ 6500)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

TOTAL



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. **XB9639D MITSUBISHI FV517JD2RDEB**

Page No. **1**

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Front corner top garnish LH <i>cm</i> ✓		1044.00	
1	Headlamp LH <i>X</i>		514.00	
1	Signal lamp LH <i>cm</i> ✓		158.00	
1	Signal lamp garnish LH <i>cm</i> ✓		318.00	
1	Center grille outer garnish <i>X</i>		681.00	
1	Front bumper <i>bt</i> ✓		960.00	
1	Front bumper inner bracket <i>X</i>		400.00	
1	Fog lamp LH <i>X</i>		285.00	
1	Fog lamp garnish LH <i>cm</i> ✓		110.00	
1	Front door LH <i>tan</i> ✓		3200.00	
1	Front door upper hinge LH <i>X</i>		189.00	
1	Front door lower hinge LH <i>?</i>		189.00	
1	Front door signal lamp LH <i>cm</i> ✓		78.00	
1	Step up upper garnish LH <i>repair</i>		1078.00	
1	Step up lower garnish LH <i>cm</i> ✓		190.00	
1	Step up lower garnish metal plate LH <i>cm</i> ✓		190.00	
1	Door pillar LH (Repair refer to labour)		0.00	
1	Bonnet (Repair refer to labour)		0.00	
Part Items Total:			9584.00	
			-25% -2396.00	
			7188.00	
<u>SPECIAL NETT ITEMS</u>				
1	Front bumper clips <i>cm</i> ✓		35.00	
1	Center grille clips <i>X</i>		25.00	
1	Bonnet company sticker <i>cm</i> ✓		400.00	<i>200</i>
SN Items Total:			460.00	
Total Parts			7648.00	



Wah Hona Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. XB9639D MITSUBISHI FV517JD2RDEB

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1400.00	750
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1400.00	750 1000
3	To perform anti-rust treatment on affected areas	90.00	40
4	To remove and repair/refit wiring system at accident damaged area and check for all electrical proper function	90.00	40
5	To remove, replace and focus headlamp LH	50.00 X	
6	To remove and refit/replace front door LH fitting, trimmings, garnish, window glass and lock mechanism	150.00	80
Labour Total :		3180.00	
TOTAL (PARTS & LABOUR):		10828.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rahul
Hp 9001268

6 days

2/3

2/11/22 @1340

Reg after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 11/11/2022 15:56 (SGT)
Reported by Both
Date of Accident 10/11/2022 09:45 (SGT)
Exact Location of Accident Near Clementi Rd, Singapore
Additional Location Information CLEMENTI ROAD TOWARDS ULU PANDAN (TRAFFIC JUNCTION)
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number XB9639D

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner DA ENGINEERING PTE LTD
Company Reg No 2XXXXX354M
Email Address MGR@DAE.SG
Mobile Phone No (Phone) +65-97589118
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Mitsubishi
Model FV517JD2RDEB
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Commercial vehicle
Transmission Manual
CC 11945

INSURANCE COMPANY

Name of Insurance Company Lonpac Insurance Bhd
Policy Number / Cover Note Number Z22VC05011333

DRIVER

Name of Driver NADARAJAN S/O KALIMUTHU
NRIC No SXXXX778B
Date Of Birth 31/08/1969

Occupation	Outdoor
Date Of Driving Pass	09/11/2007
Driving experience	15 YEARS
Gender	Male
Mobile Number	(Phone) +65-97620696
Alt. Phone Number	-
Email Address	RAJASALT@GMAIL.COM
Address	BLK 743 JURONG WEST ST. 73
Address complement	#05-05
Postcode	640743
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN AND SUMMARY

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE TOO LARGE

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP3644S
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle

No. Of Driver
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)
DOREEN TAN

Sketch Plan



ACCIDENT PD THIS UPPER BT TIMOH RD
(RIGHT TURN TO ULU PANJAN RD JUNCTION)

Describe Circumstance of the Accident

ON 10/11/2022 @ 0945HRS, MY VEHICLE A (XB9639D) WAS STATIONARY ON LANE 2 ALONG CLEMENTI RD TWDS UPPER BT TIMAH RD (RIGHT TURN TO ULU PANDAN JUNCTION) WAITING FOR TRAFFIC LIGHT TO PROCEED. WHEN TRAFFIC LIGHT TURNS GREEN, I PROCEED SLOWLY FORWARD, SUDDENLY VEHICLE B (YT3644S) CUT INTO MY LANE AND COLLIDED ONTO THE FRONT LEFT PORTION OF MY VEHICLE A (XB9639D). I HONKED AT VEHICLE B (YT3644S) BUT NO RESPONSE AND HE KEPT DRIVING OFF BRUSHING ONTO MY VEHICLE A (XB9639D). VEHICLE B (YT3644S) DID NOT STOPPED AFTER THE ACCIDENT, I THEN CHASED AFTER HIM.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Rayen

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

DUREEN TAN

2

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	354M

Vehicle Details

Vehicle No.:	XB9639D
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Nov 2022
Vehicle Make:	MITSUBISHI
Vehicle Model:	FV517JD2RDEB
Primary Colour:	White
Manufacturing Year:	2004
Engine No.:	6D24350901
Chassis No.:	FV517JA00581
Maximum Power Output:	-
Open Market Value:	\$71,953.00
Original Registration Date:	06 Jun 2005
First Registration Date:	06 Jun 2005
Transfer Count:	5
Actual ARF Paid:	\$3,598.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	31 Oct 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$12,921.00
COE Rebate Amount:	\$5,085.00
Total Rebate Amount:	\$5,085.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 11 Nov 2022

OK