

REC BY: Thuan

CS3/SMR 22 002686/113 Tny3-1

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
CD/TP/WS/TP RES/OD RES/EVA/INV/MV
To Inspect Vehicle No: _____
at Workshop m/s: _____
or _____
Insured: _____
Policy No. _____
Claims No. _____
Sub insured: _____ Excess: _____
(Client's Record)
Make of Vch: _____

N/S	O/S

By: _____ (Signature)
The vch had commenced its repair at the time of inspection.
Market Value: 7k
ICA Accident Report: _____ Consistent? Yes or No
GIA R Scene: _____ Consistent? Yes or No
Est. days: 4 days Res.: Yes or No
Loss: _____ % J Val.: Yes or No
CA: REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBD68315 Yr Rog: 12/6/09
Type: M. Car / Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Yamaha FZ6S C.C. _____
Colour: black A/C: _____ Insured / Std / NI / NA
Sp. Reading: Not avail T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: SVARS1490000007747
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Order / Jammed / Leaked / Burnt or
Brake: Order / Jammed / Leaked / Burnt or
Mod: Nil / S/Rlm / STD AIR / or
Tyre Size: F: 180/55ZR17
R: 180/55ZR17
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: _____ Rear: _____
R/Bal. S mm R/Bal. S mm
L/Bal. _____ mm L/Bal. _____ mm
D.O.A. 21/2/22 D.O.I. 23/3/22 / 600
Survey held at Candy motor
Des. of Damagos: Frl / Rear / O/S NIS / UIC / Rooflop or
The UIC / Chassis frame / Body Structure affected due to collision.

Case No	Action / Instruction
	MV: 7k
	rebat: 2211
	nu: 4789
	rr: 2.5k-3k
	23/11/22 submit lump sum \$5650 and 4 days
	(red, 3550, 39%)

Date Recd. The Pass by: 23/11/22
Date Recd. The Return by: _____
☐ : Prelim. Report
☐ : Final Report

Days Of Repair: 4
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp \$ _____
☐ : Interview \$ _____
☐ : Tech. Insp \$ _____
☐ : V/A & J \$ _____

Survey Fee: _____
Transportation: _____
S + RS: \$ _____
Fines: _____
Other: _____
Total: _____

Report Period: _____
Lump Sum: 5650