



## Case Details

Case Reference Number : TAX/11/22/2033  
Type of Repair : Accident Repair  
Vehicle Registration Number : SHF188R

Company Type : Strides Taxi Pte Ltd  
Estimation ID : EST-19831-ID  
Assigned By : Taxi Claims Manager Team

Insurance Company Name : India International Insurance Pte Ltd  
Accident Date and Time : 15/11/2022 04:15 AM  
Vehicle Age(In Months) : -

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation					Surveyor Approval					Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			REAR BUMPER REINFORCEMENT	1	360.10	360.10	25.00	270.08	Replace	0	0	Check	?
Standard	Main			COVER, RR BUMPER ASSY	1	525.40	525.40	25.00	394.05	Replace	1	394.05	Replace	cm
Standard	Main			PAD, RR BUMPER, RH & LH, 3	2	12.00	24.00	25.00	18.00	Replace	2	18.00	Replace	ne
Standard	Main			PAD, RR BUMPER, RH & LH, 2	2	4.30	8.60	25.00	6.45	Replace	2	6.45	Replace	ne
Standard	Main			PAD, RR BUMPER, RH & LH, 1	2	4.30	8.60	25.00	6.45	Replace	2	6.45	Replace	ne
Standard	Main			PAD, RR BUMPER, CTR	3	12.00	36.00	25.00	27.00	Replace	3	27.00	Replace	ne
Standard	Main			SEAL, RR BUMPER ARM, RH & LH	2	12.30	24.60	25.00	18.45	Replace	2	18.45	Replace	ne
Standard	Main			STOPPER, RR BUMPER, RH & LH	1	4.80	4.80	25.00	3.60	Replace	0	0	Not Give	Xm
Standard	Main			RETAINER, RR BUMPER, RH	1	143.60	143.60	25.00	107.70	Replace	0	0	Not Give	Xm
Standard	Main			RETAINER, RR BUMPER, LH	1	143.60	143.60	25.00	107.70	Replace	0	0	Not Give	Xm
Standard	Main			SEAL, RR BUMPER, RH	1	128.00	128.00	25.00	96.00	Replace	0	0	Not Give	Xm
Standard	Main			SEAL, RR BUMPER, LH	1	128.00	128.00	25.00	96.00	Replace	0	0	Not Give	Xm
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.80	48.00	25.00	36.00	Replace	10	36.00	Replace	ne
Standard	Main			GUARD, RR BUMPER, LOWER	1	405.00	405.00	25.00	303.75	Replace	1	303.75	Replace	de
Standard	Main			COVER, GUARD RR BUMPER LOWER	1	23.90	23.90	25.00	17.92	Replace	1	17.92	Replace	ms

Total Spare Part Cost 4,707.64

Surveyor Total 828.07

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Total Sur Total 828.07

From:

Date:

11/15/22, 5:30 PM

<https://vacswb.smrt.com.sg/Estimation.aspx>

11/15/22, 5:30 PM

Spray Coat

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			REAR BUMPER REFLECTOR ASSY, REFLEX, RH	1	42.20	42.20	25.00	31.65	Replace	0	0	Not Give	Xan
Standard	Main			REAR BUMPER REFLECTOR ASSY, REFLEX, LH	1	42.20	42.20	25.00	31.65	Replace	0	0	Not Give	Xan
Standard	Main			REAR BUMPER GROMMET SCREW	1	2.20	2.20	25.00	1.65	Replace	0	0	Not Give	Xan
Standard	Main			COVER, REAR FLOOR UNDER , RH	1	189.20	189.20	25.00	141.90	Replace	0	0	Not Give	Xan
Standard	Main			COVER, REAR FLOOR UNDER , LH	1	261.60	261.60	25.00	196.20	Replace	0	0	Not Give	Xan
Standard	Main			COVER, REAR FLOOR UNDER CENTER	1	249.10	249.10	25.00	186.83	Replace	0	0	Not Give	Xan
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check	?
Standard	Main			ANTENNA, ELECTRICAL KEY	1	78.00	78.00	10.00	70.20	Replace	0	0	Check	?
Standard	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	707.10	707.10	25.00	530.33	Replace	0	0	Check	?
Standard	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	Xan
Standard	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	1,238.40	1,238.40	25.00	928.80	Replace	0	0	Not Give	Xan
Standard	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	992.30	992.30	25.00	744.22	Replace	0	0	Not Give	Xan
Standard	Main			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	1	59.10	59.10	25.00	44.33	Replace	0	0	Not Give	Xan
Standard	Main			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	59.10	59.10	25.00	44.33	Replace	0	0	Not Give	Xan
Standard	Main			STRIDES LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	Xan
Standard	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	Xan
Total Spare Part Cost									4,707.64	Surveyor Total		828.07		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									4,707.64	Final Sur Total		828.07		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	676.00	200	



### Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY REAR PANEL	180.00	0 X17	
3	Main	TO RESPRAY BUMPER BEAM	180.00	0 X17	
4	Main	TO RESPRAY TAIL GATE	378.00	0 X17	
5	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0 X11	
Total:			1,296.00	200.00	

### Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 X17	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0 X17	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0 X17	
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0 X17	
Total:			500.00	40.00	

### Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	4,707.64	828.07
Total Labour Cost	676.00	200.00
Total Spray Painting	1,296.00	200.00
Other	500.00	40.00
Overall Total	7,179.64	1,268.07
Lump Sum Repair Option		<input type="checkbox"/>
Lump Sum Total	0.00	1,268.07
Surveyor Approved Amount		1,268.07

11/15/22, 5:30 PM

https://vacswweb.smrt.com.sg/Estimation.aspx

Estimator Assessment(\$)

Surveyor Assessment(\$)

Remarks


part by part repair / Before paint photo .FOR CHECK ITEM and  
REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP :  
9001 0066, email: rasul@lkkauto.com

Surveyor Name

Rasul

Signature





Save

Clear

Survey Date

15/11/2022

**LKK Auto Consultants hence notify  
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

**Acknowledged by Repairer**  
Signature:  
Date:

**LKK Auto Consultants hence notify  
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

**Acknowledged by Repairer**  
Signature:  
Date:

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	15/11/2022 14:47 (SGT)
Reported by	Driver
Date of Accident	15/11/2022 12:15 (SGT)
Exact Location of Accident	Hong Kah Flyover, Singapore
Additional Location Information	HONG KAH FLY OVER
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF188R
-----------------------------	---------

#### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

#### INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	D-22099115MFSH

#### DRIVER

Name of Driver	AW WEE SENG, ZART (HU WEIXING)
NRIC No	SXXXX976D
Date Of Birth	27/11/1988
Occupation	Outdoor



Date Of Driving Pass	25/11/2011
Driving experience	11 YEARS
Gender	Male
Mobile Number	(Phone) +65-68662672
Alt. Phone Number	-
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Address	11
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### PASSENGER 1

Name	UNKNOWN
Gender	Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELING ALONG HONG KAH FLYOVER TOWARDS JURONG TOWNHALL ROAD WITH ONE PASSENGER (FEMALE CHINESE) ON BOARD. THERE WAS ROAD WORK ON MY RIGHT AND A VEHICLE IN FRONT OF MY TAXI CAME TO A HALT. I APPLIED MY BRAKE TO STOP AND MANAGED TO STOP IN TIME. AFTER WHICH I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SMU9387K HAD COLLIDED ONTO THE REAR OF MY TAXI.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE TOO BIG

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMU9387K
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	CHUA ZHENG HONG
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



Long 196  
Hyover.

A - SHP 18812  
B - SMU 938712

### Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder)  
/ Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

**IMPORTANT NOTICE****SKETCH PLAN**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims,
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

Sketch Plan

15/11/2022

1



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	369K
Vehicle No.:	SHF188R
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Nov 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS SDR HATCHBACK (AUTO)
Primary Colour:	Maroon
Manufacturing Year:	2019
Engine No.:	2ZR2G30640
Chassis No.:	JTDKB3FUX03090688
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	26 Dec 2019
First Registration Date:	26 Dec 2019
Transfer Count:	0
Actual ARF Paid:	\$14,530.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Dec 2027
PARF Rebate Amount:	\$10,897.00
COE Expiry Date:	25 Dec 2027
COE Category:	A- Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$25,581.00
COE Rebate Amount:	\$16,323.00
Total Rebate Amount:	\$27,220.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 17 Nov 2022

OK